

# HellermannTyton

5/22/2019

**Subject: Change Notification**

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

| Type (Only Checked Changes Apply)   |  |  |
|---|--|--|
| <input type="checkbox"/> Production/assembly location   | <input checked="" type="checkbox"/> Material | <input type="checkbox"/> End of Life w/ replacement    |
| <input type="checkbox"/> Part Number/Ordering Code  | <input type="checkbox"/> Packaging           | <input type="checkbox"/> End of Life w/o replacement   |
| <input type="checkbox"/> Country of Origin  | <input type="checkbox"/> Point of Purchase   | <input type="checkbox"/> Additional tool/refurbishment |
| <input type="checkbox"/> Design (fit, form, function)   | <input type="checkbox"/> Point of Pick up    | <input type="checkbox"/> Cost/Lead Time                |
| <input type="checkbox"/> Engineering record (non-fit, form, function)   | <input type="checkbox"/> Supply Chain        | <input type="checkbox"/> Process                       |
| Additional Information  |  |  |
| <b>From: UR066NH0HS</b>   |  | <b>To: UR66G001</b>                                    |
| <p><b>As a risk mitigation for plastic resin supply, we are introducing an alternative resin. This allows flexibility to maneuver dynamic market conditions. These resins are comparable, both fulfilling all product specifications according to the print.</b></p> <p><b>This change is effective TBD and will be conducted as a running change. PPAP, or product data as according to print, will be provided upon request, as it becomes available.</b></p> |  |  |
| Scope   |  |  |
| <b>HT PN / Ordering Code</b>  | <b>Customer PN</b>                           | <b>Change Effective*</b>                               |
| SNP1.5GHS0M4  | 1436-1136-ND                                 | 6/21/2019  |
| SNP6GHS0C2  | 1436-1340-ND                                 | 6/21/2019  |
| SNP70GHS0C2   | SNP70GHS0C2                                  | 6/21/2019  |

\*Effective date is subject to change based on availability

We ask that you please acknowledge this notification by 5/31/2019, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Todd Franz  
 Quality Project Administrator  
 Office: 414 355 1130 x 8656  
 Email: tfranz@htamericas.com