

## Product Change Notice

# 3M™ Boardmount Socket – 2 mm x 2 mm Str. Surface Mount, – 1502 and 1532 Series

Issue Number: 758

Date: June 3, 2010 (Revised from May 28<sup>th</sup> version)

## Product Change

In order to improve manufacturability, 3M is changing the insulator material of the surface mount versions of Boardmount Sockets, 1502 and 1532 Series from glass-filled PCT to glass-filled LCP.

Product specifications, performance, price and delivery will remain unchanged. The revised product is functionally equivalent to, or better than, the unchanged version of the product. This change will affect tech sheet numbers TS0519 and TS0521.

3M will begin shipping products made with LCP for regular orders as existing PCT insulator inventory is exhausted. Because of this, exact switchover dates will vary by pin count and body style.

Last time buys (LTB) can be filled by special request. Customers who require the original PCT insulator material must contact 3M via the methods noted below and request a LTB, on or before close of business (Central US Time) June 30, 2010. 3M will, subject to satisfaction of minimum order requirements, endeavor to supply a final quantity of PCT parts (subject to availability).

Customers who do not require LTB need do nothing. They will begin receiving parts with LCP insulators as soon as current inventory is exhausted.

ITEM DESC	MMM ID NBR
150206-2000-RB-WB	80000911158
150206-2000-TB	80130083324
150208-2000-RB	80000903502
150208-2000-RB-WB	80000911588
150208-2000-TH-WB	80610522361
150210-2000-RB-WB	80000903684
150210-2020-RB-WB	80001208307
150212-2000-RB	80000912990

## Product Change Notice

### 3M™ Boardmount Socket – 2 mm x 2 mm Str. Surface Mount, Str. and RA Plated Through-Hole – 1502 and 1532 Series

ITEM DESC	MMM ID NBR
150212-2000-RB-WB	80001211251
150212-2020-RB	80000903510
150212-2020-RB-WB	80001211269
150214-2020-RB	80001212614
150216-2000-RB	80000917999
150216-2000-RB-WB	80001224205
150216-2000-TB-WB	80001213281
150216-2020-RB-WB	80000903692
150220-2000-RB	80000903528
150220-2000-RB-WD	80001211277
150220-2000-TB	80130082300
150220-2000-TB-WD	80001213299
150220-2020-RB	80000917460
150220-2020-RB-WD	80001151515
150224-2000-RB-WD	80000903536
150226-2020-RB-WD	80000903718
150230-2020-RB	80000903544
150230-2020-TB	80130082896
150232-2020-RB-WE	80001211301

ITEM DESC	MMM ID NBR
150234-2000-RB	80000903569
150234-2000-TH	80130082649
150234-2020-RB	80000911356
150240-2000-RB	80000902306
150240-2020-RB	80000903585
150244-2000-RB	80001200213
150244-2000-RB	80001206673
150244-2000-RB-WF	80001205956
150244-2020-RB	80000903593
150244-2020-TB	80001201286
150250-2000-RB	80000903601
150250-2020-RB	80000903619
150250-2020-RB-WF	80000903734

## Product Change Notice

### 3M™ Boardmount Socket – 2 mm x 2 mm Str. Surface Mount, Str. and RA Plated Through-Hole – 1502 and 1532 Series

ITEM DESC	MMM ID NBR
150252-2020-RB	80000903627
150260-2020-RB	80000903635
153204-2000-RB	80000903742
153204-2000-RB-WA	80000903973
153208-2000-RB	80001152208
153208-2000-RB	80001211434
153208-2000-RB-WB	80000913006
153208-2020-RB	80000903759
153208-2020-RB-WB	80001151788
153210-2000-RB-WB	80001211442
153210-2020-RB	80000903767
153210-2020-RB-WB	80001211459
153212-2000-RB-WB	80001211467
153212-2020-RB-WB	80001211475
153214-2000-RB-WB	80000903999
153214-2020-RB	80000903783
153216-2000-RB	80001211483
153216-2020-RB	80000903809
153216-2020-RB-WB	80000904013
153220-2020-RB-WC	80000904021
153220-2020-TB	80000931289
153222-2020-RB-WD	80000904039
153224-2000-RB-WD	80000904047
153226-2000-RB-WD	80000904062
153226-2020-RB	70010017864
153230-2020-RB	80000903825
153230-2020-TB	80130072574
153232-2020-RB	80000903833
153236-2020-RB	80000903841
153236-2020-TB	80610367353
153240-2020-RB	80000903858
153240-2020-TB	80130072624

ITEM DESC	MMM ID NBR
153242-2020-RB	80000903866
153244-2000-RB	80001200221
153244-2020-RB	80000903874
153246-2000-RB-WF	80000903882
153246-2000-TB-WF	80400016285
153250-2000-RB	80001201708
153250-2000-RB	80001211491
153250-2020-RB-WF	80000904088
153256-2020-RB	80000903916
153260-2020-RB	80000903924
153260-2020-TB	80130072723

## Product Change Notice

# 3M™ Boardmount Socket – 2 mm x 2 mm Str. Surface Mount, Str. and RA Plated Through-Hole – 1502 and 1532 Series

## Contact Information

### In the USA

3M US Customer Service  
800-225-5373

### Outside the USA

Please contact your local 3M subsidiary or authorized distributor. Visit [www.3Mconnector.com](http://www.3Mconnector.com) and click “Where to Buy.”

3M is a trademark of 3M Company

### Important Notice

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product which are not contained in 3M's current publications, or any contrary statements contained on your purchase order shall have no force or effect unless expressly agreed upon, in writing, by an authorized officer of 3M.

### Warranty; Limited Remedy; Limited Liability.

This product will be free from defects in material and manufacture for a period of one year from the time of purchase. **3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.** If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. **Except where prohibited by law, 3M will not be liable for any indirect, special, incidental or consequential loss or damage arising from this 3M product, regardless of the legal theory asserted.**



### Electronic Solutions Division

#### Interconnect Products

6801 River Place Blvd.  
Austin, TX 78726-9000  
1-800-225-5373  
[www.3Mconnector.com](http://www.3Mconnector.com)

© 3M 2010 All Rights Reserved.