

Obsolete Products - RP15-OF(W) DC/DC Converter

Dear customers,

We herewith inform you about the following DC/DC products being made obsolete.

| Article # | EoL Product | Alternate Article # | Alternate Part |
|-----------|------------------|---------------------|----------------|
| 30900042 | RP15-243.3SOF/P | none | Discontinued |
| 30900040 | RP15-243.3SOF/N | none | Discontinued |
| 30900006 | RP15-2405SOF/P | none | Discontinued |
| 30900004 | RP15-2405SOF/N | none | Discontinued |
| 30900018 | RP15-2412SOF/P | none | Discontinued |
| 30900016 | RP15-2412SOF/N | none | Discontinued |
| 30900030 | RP15-2415SOF/P | none | Discontinued |
| 30900028 | RP15-2415SOF/N | none | Discontinued |
| 30900090 | RP15-483.3SOF/P | none | Discontinued |
| 30900088 | RP15-483.3SOF/N | none | Discontinued |
| 30900054 | RP15-4805SOF/P | none | Discontinued |
| 30900052 | RP15-4805SOF/N | none | Discontinued |
| 30900066 | RP15-4812SOF/P | none | Discontinued |
| 30900064 | RP15-4812SOF/N | none | Discontinued |
| 30900078 | RP15-4815SOF/P | none | Discontinued |
| 30900076 | RP15-4815SOF/N | none | Discontinued |
| 30900039 | RP15-243.3SOF | none | Discontinued |
| 30900003 | RP15-2405SOF | none | Discontinued |
| 30900015 | RP15-2412SOF | none | Discontinued |
| 30900027 | RP15-2415SOF | none | Discontinued |
| 30900087 | RP15-483.3SOF | none | Discontinued |
| 30900051 | RP15-4805SOF | none | Discontinued |
| 30900063 | RP15-4812SOF | none | Discontinued |
| 30900075 | RP15-4815SOF | none | Discontinued |
| 30900048 | RP15-243.3SOFW/P | none | Discontinued |
| 30900046 | RP15-243.3SOFW/N | none | Discontinued |
| 30900012 | RP15-2405SOFW/P | none | Discontinued |
| 30900010 | RP15-2405SOFW/N | none | Discontinued |
| 30900024 | RP15-2412SOFW/P | none | Discontinued |
| 30900022 | RP15-2412SOFW/N | none | Discontinued |
| 30900036 | RP15-2415SOFW/P | none | Discontinued |
| 30900034 | RP15-2415SOFW/N | none | Discontinued |
| 30900096 | RP15-483.3SOFW/P | none | Discontinued |
| 30900094 | RP15-483.3SOFW/N | none | Discontinued |
| 30900060 | RP15-4805SOFW/P | none | Discontinued |
| 30900058 | RP15-4805SOFW/N | none | Discontinued |
| 30900072 | RP15-4812SOFW/P | none | Discontinued |

| | | | |
|----------|-----------------|------|--------------|
| 30900070 | RP15-4812SOFW/N | none | Discontinued |
| 30900084 | RP15-4815SOFW/P | none | Discontinued |
| 30900082 | RP15-4815SOFW/N | none | Discontinued |
| 30900045 | RP15-243.3SOFW | none | Discontinued |
| 30900009 | RP15-2405SOFW | none | Discontinued |
| 30900021 | RP15-2412SOFW | none | Discontinued |
| 30900033 | RP15-2415SOFW | none | Discontinued |
| 30900093 | RP15-483.3SOFW | none | Discontinued |
| 30900057 | RP15-4805SOFW | none | Discontinued |
| 30900069 | RP15-4812SOFW | none | Discontinued |
| 30900081 | RP15-4815SOFW | none | Discontinued |

EoL Notice 23-Sep-2020
EoL Last Time Buy Date 31-Dec-2020
EoL Last Delivery Date 31-Mar-2021



Power GmbH

Authorized Signature

Tel.: +43(0)7612-88325-700
Fax: +43(0)7612-88325-801

i.A. Steve Roberts, Product Innovation Manager
Signed for and on behalf of RECOM Power GmbH

Should individual customers require assistance with other alternative power supply solutions, please contact RECOM for assistance:

Europe: Tel: +49 (0) 6102-88381-0 or info@recom-electronic.com
Asia: Tel: +65 62768795 or enquiry@recom-power.com
North-America: Tel: +1-720-386-0400 or admin@recom-power.com