

Product Change Notice

Date:	March 14, 2023
Overview:	Label change for select models
Reason for Change:	Production location change
Affected Part No(s):	Please see part listing on page 2 of this PCN
Design Change Detail:	Production for select models is shifting from Mulfingen, Germany to Tapolca, Hungary, so the labels will be updated from saying "Made in Germany" to "Made by ebm-papst HU-T"
Effective Date:	Running change beginning in April of 2023
Last Time Buy Deadline:	N/A
Pricing:	No change
ebm-papst employee:	Jeannine Zenobi
Attachments:	Affected part numbers
Comments:	All affected models produced starting the week of April 3, 2023 will be made by ebm-papst Hungary. Depending on existing inventory at ebm-papst Inc. in Farmington, CT, it is possible that some parts may still be marked "Made in Germany" for deliveries after April of 2023.

Affected Part Numbers

8300100524	R2E133-BH66-34	R2E133-RA29-11	R2E175-RA66-15
R2E097-AD01-05	R2E133-BH66-35	R2E140-BI52-05	R2S133-AE17-05
R2E097-AD01-16	R2E133-BH66-36	R2E140-BI54-10	R2S133-AE17-15
R2E108-AA01-05	R2E133-BH66-38	R2E140-BR52-19	R2S133-AE17-17
R2E108-AA05-31	R2E133-BH66-40	R2E140-BR52-20	R2S133-AE17-18
R2E108-AC01-22	R2E133-BH66-42	R2E140-BR64-21	R2S133-AE17-22
R2E108-AC01-28	R2E133-BH66-43	R2E140-BR64-22	R2S133-AE17-25
R2E108-AC04-30	R2E133-BH66-44	R2E140-BR64-23	R2S133-AE17-41
R2E108-AG63-05	R2E133-BH66-46	R2E140-BU57-16	R2S133-AE17-43
R2E120-BB74-15	R2E133-BH66-48	R2E140-BU68-14	R2S133-AE17-45
R2E120-BB76-11	R2E133-BH66-49	R2E140-BU76-11	R2S133-AE17-46
R2E120-BB76-21	R2E133-BH72-13	R2E140-BU76-12	R2S133-AE77-15
R2E120-BC80-12	R2E133-BH72-14	R2E140-CC66-09	R2S133-AE77-18
R2E120-BD76-09	R2E133-BH72-16	R2E150-BB74-10	R2S133-AE77-22
R2E120-BD76-10	R2E133-BH72-24	R2E160-BB81-12	R2S133-AE77-27
R2E120-BE52-09	R2E133-BH72-25	R2E160-BE60-11	R2S133-AF50-12
R2E133-AR04-09	R2E133-BH72-26	R2E160-BE76-10	R2S133-AF50-15
R2E133-AR04-10	R2E133-BH72-30	R2E160-RA63-01	R2S133-AF50-18
R2E133-BC52-09	R2E133-BH72-31	R2E160-RA89-05	R2S133-AF50-34
R2E133-BC54-10	R2E133-BH72-34	R2E160-RB51-05	R2S175-AA07-39
R2E133-BH66-05	R2E133-BH72-41	R2E175-AR66-09	R2S175-AA49-35
R2E133-BH66-07	R2E133-BH72-47	R2E175-AR66-12	R2S175-AB56-01
R2E133-BH66-12	R2E133-BH82-24	R2E175-AR70-05	R2S175-AB56-21
R2E133-BH66-14	R2E133-BH82-34	R2E175-AR70-10	R2S175-AB56-30
R2E133-BH66-15	R2E133-BH94-18	R2E175-AR70-13	R2S175-AB56-34
R2E133-BH66-16	R2E133-BH94-22	R2E175-AR70-14	R2S175-AB56-42
R2E133-BH66-20	R2E133-BH96-36	R2E175-AR72-05	R2S175-AB56-55
R2E133-BH66-24	R2E133-BI76-09	R2E175-AR72-11	R2S175-AB56-56
R2E133-BH66-25	R2E133-RA03-01	R2E175-BA62-12	R2S175-AB60-18
R2E133-BH66-27	R2E133-RA03-03	R2E175-BA62-14	R2S175-AB60-38
R2E133-BH66-30	R2E133-RA03-12	R2E175-BA78-10	R2S175-AB60-58
R2E133-BH66-31	R2E133-RA03-13	R2E175-BA78-11	
R2E133-BH66-32	R2E133-RA29-02	R2E175-BA78-13	
R2E133-BH66-33	R2E133-RA29-10	R2E175-RA30-19	

No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing