



PCN - 12 093

Issue Date: September 20 2012

Product Name:	MILLIPACS			
	MILLIPACS HEADER CONNECTORS			
Product Manager:	VARGHESE MATHEW			
Subject:	Notification of Planned Change			
Distribution:	GLOBAL			
Type of Change:	Process Change			
Change Description:	<p>The shielding pin's on the side walls of HM2 Millipac's Header Connectors are currently provided precious metal plating on both the inner mating area and the outer non-mating area.</p> <p>In future, FCI will provide Precious Metal Plating only on the inner area of the pins which gets connected with the top shield of the mated receptacle connector. This change will have no impact on the fit, function or performance of the connector.</p>			
Reason for Change:	Optimization of Plating Process			
Affected Parts:	Attached List			
Effective Date of Change:	December	30	2012	
Last Time Buy Date:	N/A	N/A	N/A	
Last Disty Return Date:	N/A	N/A	N/A	
Last Time Shipment Date	N/A	N/A	N/A	
Datasheet Attached?	N/A			
Qual/Test Data Attached?	N/A			
Samples Availability Date:	September	20	2012	
Available Alternatives?	N/A			
Questions?	<i>Contact your local FCI Representative, or</i>			
	VARGHESE MATHEW			
	00 91 484 6611532		VMathew@fci.com	