



Product Change Notification

TE Connectivity

Product Change Notification: E-20-012311

PCN Date: 09-SEP-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

P2 relay, Internal armature plating change.

Description of Changes

Introduced off a new plating for P2 relays due to external discontinuation of current plating process and supplier. Old plating: AgC, New released and approved plating : Cu. New plating is included in UL approval process. Our UL ratings are, where possible, tested to meet increased temperatures ratings aiming an increasind performance level. UL file update is in process and to be finished before the implementation of the change.

Reason for Changes:

Product Improvement. product improvement

Estimated Dates:

Last Order Date (Obsolete Parts Only): **First Date To Ship** (Changed Parts Only):

17-DEC-2020

Last Ship Date (Obsolete Parts Only): **Last Date for Mixed Shipments:** (Changed Parts Only):

30-MAR-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393788-1	NO			"V23079A1003B301"			
1-1393788-6	NO			"V23079A1005B301"			
1-1422002-0	NO						
1393788-3	NO			"V23079A1001B301"			
1422006-1	NO						
1422006-4	NO						
1422006-5	NO						
1422007-8	NO						
3-1393788-6	NO			"V23079B1203B301"			
3-1393788-7	NO			"V23079B1205B301"			
3-1393788-9	NO			"V23079B1206B301"			
3-1393789-5	NO			"V23079A2001B301"			
3-1393789-7	NO			"V23079A2003B301"			
3-1393789-8	NO			"V23079A2006B301"			
4-1393788-1	NO			"V23079B1208B301"			
4-1393789-3	NO			"V23079D2001B301"			
4-1393789-5	NO			"V23079D2003B301"			
4-1393789-7	NO			"V23079D2008B301"			
4-1393789-8	NO			"V23079D2011B301"			
5-1393788-5	NO			"V23079D1001B301"			
5-1393788-7	NO			"V23079D1003B301"			
5-1393788-8	NO			"V23079D1005B301"			
5-1393789-0	NO			"V23079G2002B301"			
5-1393789-1	NO			"V23079G2003B301"			
5-1393789-3	NO			"V23079G2006B301"			
5-1393789-4	NO			"V23079G2008B301"			
6-1393788-8	NO			"V23079E1201B301"			
6-1419120-6	NO			"V23079A2008B301"			
7-1393788-0	NO			"V23079E1205B301"			
7-1393788-1	NO			"V23079E1208B301"			
7-1393788-8	NO			"V23079G1005B301"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393788-1	NO			"V23079A1003B301"			
1-1393788-6	NO			"V23079A1005B301"			
1393788-3	NO			"V23079A1001B301"			
1422007-8	NO						
3-1393788-7	NO			"V23079B1205B301"			
3-1393788-9	NO			"V23079B1206B301"			
3-1393789-5	NO			"V23079A2001B301"			
3-1393789-7	NO			"V23079A2003B301"			
3-1393789-8	NO			"V23079A2006B301"			
4-1393789-3	NO			"V23079D2001B301"			
4-1393789-5	NO			"V23079D2003B301"			
5-1393788-5	NO			"V23079D1001B301"			
5-1393788-7	NO			"V23079D1003B301"			
5-1393788-8	NO			"V23079D1005B301"			
5-1393789-1	NO			"V23079G2003B301"			
6-1393788-8	NO			"V23079E1201B301"			
7-1393788-0	NO			"V23079E1205B301"			
7-1393788-1	NO			"V23079E1208B301"			
7-1393788-8	NO			"V23079G1005B301"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1422002-0	NO						
1422006-1	NO						
1422006-4	NO						
1422007-8	NO						
3-1393788-9	NO			"V23079B1206B301"			
3-1393789-8	NO			"V23079A2006B301"			
4-1393788-1	NO			"V23079B1208B301"			
4-1393789-7	NO			"V23079D2008B301"			
4-1393789-8	NO			"V23079D2011B301"			
5-1393789-0	NO			"V23079G2002B301"			
5-1393789-3	NO			"V23079G2006B301"			
5-1393789-4	NO			"V23079G2008B301"			
6-1419120-6	NO			"V23079A2008B301"			
7-1393788-1	NO			"V23079E1208B301"			
7-1393788-8	NO			"V23079G1005B301"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393788-1	NO			"V23079A1003B301"			
1-1393788-6	NO			"V23079A1005B301"			
1-1422002-0	NO						
1393788-3	NO			"V23079A1001B301"			
1422006-1	NO						
1422006-4	NO						
1422007-8	NO						
3-1393788-7	NO			"V23079B1205B301"			
3-1393788-9	NO			"V23079B1206B301"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-1393789-5	NO			"V23079A2001B301"			
3-1393789-7	NO			"V23079A2003B301"			
3-1393789-8	NO			"V23079A2006B301"			
4-1393788-1	NO			"V23079B1208B301"			
4-1393789-3	NO			"V23079D2001B301"			
4-1393789-7	NO			"V23079D2008B301"			
4-1393789-8	NO			"V23079D2011B301"			
5-1393788-5	NO			"V23079D1001B301"			
5-1393788-7	NO			"V23079D1003B301"			
5-1393788-8	NO			"V23079D1005B301"			
5-1393789-0	NO			"V23079G2002B301"			
5-1393789-1	NO			"V23079G2003B301"			
5-1393789-3	NO			"V23079G2006B301"			
5-1393789-4	NO			"V23079G2008B301"			
6-1393788-8	NO			"V23079E1201B301"			
6-1419120-6	NO			"V23079A2008B301"			
7-1393788-0	NO			"V23079E1205B301"			
7-1393788-1	NO			"V23079E1208B301"			
7-1393788-8	NO			"V23079G1005B301"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393788-1	NO			"V23079A1003B301"			
1-1422002-0	NO						
1393788-3	NO			"V23079A1001B301"			
1422006-1	NO						
1422006-4	NO						
1422006-5	NO						
1422007-8	NO						
3-1393788-6	NO			"V23079B1203B301"			
3-1393789-8	NO			"V23079A2006B301"			
4-1393788-1	NO			"V23079B1208B301"			
4-1393789-7	NO			"V23079D2008B301"			
4-1393789-8	NO			"V23079D2011B301"			
5-1393788-5	NO			"V23079D1001B301"			
5-1393789-0	NO			"V23079G2002B301"			
5-1393789-3	NO			"V23079G2006B301"			
5-1393789-4	NO			"V23079G2008B301"			
6-1419120-6	NO			"V23079A2008B301"			
7-1393788-1	NO			"V23079E1208B301"			
7-1393788-8	NO			"V23079G1005B301"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-1393788-5	NO			"V23079D1001B301"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393788-1	NO			"V23079A1003B301"			
1-1422002-0	NO						
1393788-3	NO			"V23079A1001B301"			
1422006-1	NO						
1422006-4	NO						
1422006-5	NO						
1422007-8	NO						
3-1393788-6	NO			"V23079B1203B301"			
3-1393789-8	NO			"V23079A2006B301"			
4-1393788-1	NO			"V23079B1208B301"			
4-1393789-7	NO			"V23079D2008B301"			
4-1393789-8	NO			"V23079D2011B301"			
5-1393788-5	NO			"V23079D1001B301"			
5-1393789-0	NO			"V23079G2002B301"			
5-1393789-3	NO			"V23079G2006B301"			
5-1393789-4	NO			"V23079G2008B301"			
6-1419120-6	NO			"V23079A2008B301"			
7-1393788-1	NO			"V23079E1208B301"			
7-1393788-8	NO			"V23079G1005B301"			