

Product



End of Life Announcement

By: Tommy Lee, Product Specialist

Date: August 24, 2018

Dear Fluke and Pomona Distributor:

The Pomona products in the table mentioned below will no longer be available for sales.
Effective dates varies (see below).

Please start ordering the concerning replacement parts as soon as possible!

This letter is your notification of our product change.

PLEASE INFORM ALL RELEVANT PERSONNEL WITHIN YOUR ORGANIZATION.



Item Number	Item Description	Obsolete Date	Notes
1942445	1081-60-4,MINI BANANA PLUG PATCH CORD (YELLOW) MTO	9/28/2018	There is no replacement.
1942450	1081-60-6,MINI BANANA PLUG PATCH CORD (BLUE) MTO	9/28/2018	There is no replacement.
1937166	1794,BNC (F)/PJ-068 PHONE PLUG	9/28/2018	There is no replacement.
1930530	2112,BIND POST/PJ051	9/28/2018	There is no replacement.
1927906	2BC-MG-36,DBL BANANA/MINI CL, RG58C/U	9/28/2018	There is no replacement.
1914345	4846-K-24,SMA (M), RG174/U	9/28/2018	There is no replacement.
1914361	4846-K-48,SMA (M), RG174/U	9/28/2018	There is no replacement.
1914404	4846-K-60,SMA (M), RG174/U	9/28/2018	There is no replacement.
1916370	5008,BNC (F)/.090 VIDEO PLUG	9/28/2018	There is no replacement.
1916482	5019-60,GRABBER/BANTAM PLUG	9/28/2018	There is no replacement.
1916502	5019N-60,BANTAM/2 MINI GRABBERS, 60 INCHES	9/28/2018	There is no replacement.
1906687	5795A,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6495 (PN 1898438).
1906693	5800A/POM,OSCILLOSCOPE PROBE	12/14/2018	There is no replacement.
1906721	5806A,OSCILLOSCOPE PROBE	8/24/2018	May be replaced by the 6500 (PN 1898489).
1906763	5812A,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6497 (PN 1898450).
1906824	5827A,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6498 (PN 1898461).
1908182	6049A,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6493 (PN 1898414).
1908203	6069A,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6495 (PN 1898438).

1908641	6101A/POM,OSCILLOSCOPE PROBE	8/24/2018	May be replaced by the 6494 (PN 1898423).
1908652	6102A,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6497 (PN 1898450).
1909786	6256,7/16 DIN MALE/N MALE	8/24/2018	There is no replacement.
1909799	6257,7/16 DIN MALE/N FEMALE	8/24/2018	There is no replacement.
1909814	6260,7/16 DIN FEMALE/N FEMALE	8/24/2018	There is no replacement.
1901580	6265,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6493 (PN 1898414).
1901598	6266,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6499 (PN 1898477).
1901604	6267,ACCESSORIES, OSC PROBE	12/14/2018	There is no replacement.
1902994	6331-96,DUAL BANTAM EA. END CABLE	9/28/2018	There is no replacement.
1898726	6519,BNC TO MINI-WECO ADAPTER	9/28/2018	There is no replacement.
3094151	72950,SMA PLUG STRAIGHT CRIMP, REVERSE POLARITY, RG174, 188, 316	9/28/2018	There is no replacement.
3094235	72958,SMA PLUG R/A CRIMP, RG58	9/28/2018	There is no replacement.
3094802	73015,MCX PLUG STRAIGHT SEMI-RIGID, RG405	9/28/2018	There is no replacement.
3095011	73039,MMCX JACK STRAIGHT EDGE CARD	9/28/2018	There is no replacement.
3388000	73058,UHF JACK TO JACK ADAPTER	9/28/2018	There is no replacement.
3388017	73059,UHF STRAIGHT PLUG, SOLDER TYPE, RG8, 9, 11, 63, 87A, 213, 214, 225	9/28/2018	There is no replacement.
3388153	73063-BB-12,MMCX PLUG TO MMCX PLUG, RG316/U, 12 INCH	9/28/2018	There is no replacement.
3388215	73064-BB-36,MMCX PLUG TO MMCX RIGHT-ANGLE PLUG, RG316/U, 36 INCH	9/28/2018	There is no replacement.
3388314	73067-BB-12,MCX PLUG TO MCX PLUG, RG316/U, 12 INCH	9/28/2018	There is no replacement.
3189459	EM1126-96-0#,BANANA PLUG/PIN TIP PLUG (BLACK) MTO BULK	9/28/2018	There is no replacement.
3189471	EM1126-96-2#,BANANA PLUG/PIN TIP PLUG (RED) MTO BULK	9/28/2018	There is no replacement.
3371820	EM1166-144-0#,ALLIG CL, BANANA PLUG (BLACK), MTO BULK	9/28/2018	There is no replacement.
2431170	EM2882-C-18,PIN TIP/BNC (M) RG58C/U MTO	9/28/2018	There is no replacement.
3408629	EM2948-120-0#,BANANA PLUG PATCH CORD, GOLD (BLACK), MTO BULK	9/28/2018	There is no replacement.
3408641	EM2948-120-2#,BANANA PLUG PATCH CORD, GOLD (RED), MTO BULK	9/28/2018	There is no replacement.
3050075	EM3014-12-0#,MINI BANANA PLUG PATCH CORD (BLACK) MTO BULK	9/28/2018	There is no replacement.
3050082	EM3014-12-2#,MINI BANANA PLUG PATCH CORD (RED) MTO BULK	9/28/2018	There is no replacement.
3190648	EM3782-12-8#,MINIGRABBER/BANANA PLUG (GRAY), MTO BULK	9/28/2018	There is no replacement.
3190666	EM3782-12-9#,MINIGRABBER/BANANA PLUG (WHITE), MTO BULK	9/28/2018	There is no replacement.
3190630	EM3782-24-7#,MINIGRABBER/BANANA PLUG (VIOLET), MTO BULK	9/28/2018	There is no replacement.
3190653	EM3782-24-8#,MINIGRABBER/BANANA PLUG (GRAY), MTO BULK	9/28/2018	There is no replacement.
3184754	EM3782-36-8#,MINIGRABBER/BANANA PLUG (GRAY), MTO BULK	9/28/2018	There is no replacement.
3242692	EM3782-48-1#,MINIGRABBER/BANANA PLUG (BROWN), MTO BULK	9/28/2018	There is no replacement.
3242704	EM3782-48-3#,MINIGRABBER/BANANA PLUG (ORANGE), MTO BULK	9/28/2018	There is no replacement.
3315733	EM3782-48-9#,MINIGRABBER/BANANA PLUG (WHITE), MTO BULK	9/28/2018	There is no replacement.
2540800	EM4650-60-0#,MINIGRABBER/BANANA PLUG (BLACK) MTO BULK	9/28/2018	There is no replacement.
2555053	EM4702-18-0#,BANANA PLUG/BANANA JACK, (BLACK), MTO BULK	9/28/2018	There is no replacement.
2555066	EM4702-18-2#,BANANA PLUG/BANANA JACK, (RED), MTO BULK	9/28/2018	There is no replacement.
3410635	EM4702-60-0#,BANANA PLUG/BANANA JACK (BLACK), MTO BULK	9/28/2018	There is no replacement.
3782508	EM4702-60-2#,,BANANA PLUG/BANANA JACK MTO BULK	9/28/2018	There is no replacement.

2118619	EM5223-168,3 LUG TRIAX, BELDEN 9222 - MTO	9/28/2018	There is no replacement.
4907202	EM5223-192#,3 LUG TRIAX, BELDEN 9222 MTO BULK	9/28/2018	There is no replacement.
3035197	EM5697-600#,BNC (M) CABLE W/O BOOT, MTO BULK	9/28/2018	There is no replacement.
2557143	EM6283-C-144#,DBL BANANA PLUG W/SAFETY SHROUD, 144 INCHES, MTO BULK	9/28/2018	There is no replacement.
3208633	EMAL-B-36-4#,ALLIG CLIP PATCH CORD (YELLOW), MTO BULK	9/28/2018	There is no replacement.
3208657	EMAL-B-36-6#,ALLIG CLIP PATCH CORD (BLUE), MTO BULK	9/28/2018	There is no replacement.
3208684	EMAL-B-36-9#,ALLIG CLIP PATCH CORD (WHITE), MTO BULK	9/28/2018	There is no replacement.
4241404	EMB-84-0#,BANANA PLUG PATCH CORD (BLACK) , MTO BULK	9/28/2018	There is no replacement.
4241419	EMB-84-2#,BANANA PLUG PATCH CORD (RED) , MTO BULK	9/28/2018	There is no replacement.
4903296	EMHB-360-0#,BANANA PLUG PATCH CORD - (BLACK) MTO BULK	9/28/2018	There is no replacement.
4903308	EMHB-360-2#,BANANA PLUG PATCH CORD - (RED) MTO BULK	9/28/2018	There is no replacement.
2125724	EMHB-36-3,BANANA PLUG PATCH CORD (ORANGE) MTO	9/28/2018	There is no replacement.
2424472	EMHB-48-9,BANANA PLUG PATCH CORD (WHITE) MTO	9/28/2018	There is no replacement.
2572021	EMHB-60-1#,BANANA PLUG PATCH CORD - (BROWN) MTO BULK	9/28/2018	There is no replacement.
2572039	EMHB-60-5#,BANANA PLUG PATCH CORD - (GREEN) MTO BULK	9/28/2018	There is no replacement.
2572056	EMHB-60-6#,BANANA PLUG PATCH CORD - (BLUE) MTO BULK	9/28/2018	There is no replacement.
2573959	EMHB-60-9#,BANANA PLUG PATCH CORD - (WHITE) MTO BULK	9/28/2018	There is no replacement.
2654457	EMHB-72-4#,BANANA PLUG PATCH CORD (YELLOW), MTO BULK	9/28/2018	There is no replacement.
4683375	EMP-48-0#,PIN TIP PLUG PATCH CORD (BLACK), MTO BULK	9/28/2018	There is no replacement.
4683382	EMP-48-2#,PIN TIP PLUG PATCH CORD (RED), MTO BULK	9/28/2018	There is no replacement.
1888373	P-12-4,PIN TIP PLUG PATCH CORD (YELLOW) MTO	9/28/2018	There is no replacement.
1889167	SP150B,OSCILLOSCOPE PROBE	12/14/2018	May be replaced by the 6499 (PN 1898477).
1777523	6109, 44 PIN SOIC TEST CLIP	9/28/2018	There is no replacement.