



Product Change Notification (PCN)

PCN Number	508839	Date Issued	February 26, 2021
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Reason for Short Notice	Special Request		
Assessment of Change	Passed FAI		
Internal Molex Qualification Date	May 07, 2021		
Sample Availability Date (Changed Part)	May 07, 2021		
Planned Implementation Date	May 16, 2021		
Method of Identifying Change	Date code		

RELEASED

Before Change

Overview

- Aging die condition for 87438 terminal.

After Change

Overview

- The purpose of this letter is to built new second die for 87438 terminal series. The reason for the change is to supply better quality of 87438 terminal due to aging die condition at Molex Malaysia
- Molex Malaysia Part Number(s)Affected: 87438 series
- There is no impact of the change since there is no change in design, process on the die, therefore no change in the Molex terminal part number will occur either
- Qualification Reports and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508839**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #
508839	780481043
508839	874380243
508839	874380343
508839	874380443
508839	874380543
508839	874380643
508839	874380743
508839	874380843
508839	874381043
508839	874381143
508839	874381243
508839	874381543
508839	874381543
508839	2027060543

Part numbers affected:

87438-0243

87438-0943