



Product Change Notification (PCN)

PCN Number	509162	Date Issued	July 22, 2020
Reason for Change	Manufacturing Process Change (Molex)		
Change Type Description	This letter is to inform you that the manufacturing process for the part(s) identified in this notice is changing. No changes will be made to the product as a result of this process change.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date		
Internal Molex Qualification Date	July 29, 2020		
Sample Availability Date (Changed Part)	July 29, 2020		
Planned Implementation Date	January 22, 2021		
Method of Identifying Change	Date code		

Before Change

Before



After

- Remove the metal shell solder tail pre-tinning process



After Change

Overview

- Due to the metal shell solder tail pre-tinning process make that metal shell easy filth and needs to cleaning , So we suggestion to removing the pre-tinning process.
- Product Impact
 - No impact to fit, form or function
- Part Number Impact
 - See attached list
- PPAP and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:509162**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #
509162	480250002
509162	480250091
509162	480251090
509162	480254000
509162	480749101