

Product Obsolescence Memo

W A F E R S

March 7, 2019

Bourns® Model FLxxx, HRxxx, SDxxx, TRxxx, TTxxx, TUxxx and TWxxx to be Discontinued

Due to circumstances beyond Bourns' control, our current wafer supplier is no longer able to provide 4-inch wafers. Bourns has identified the select models listed below to be transferred to an End of Product Life status. As a consequence, availability is limited to (i) remaining inventory of 4-inch wafers, (ii) work-in-process on Bourns' production lines and (iii) stock on hand in Bourns' warehouse(s).

Regrettably, replacement products are not available at this time. Customers must notify Bourns in writing within 30 days of receipt of this notification if they consider the discontinued product to be "sole sourced" by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate end-of-life purchase for the discontinued products. Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for these products will be considered non-cancellable and non-returnable.

Obsolete Part Numbers				
FL200VQ	TT418YQ	TU155YQ	TU914YQ	TW809YQ
HR760EQ	TT422YQ	TU355YQ	TU916YQ	TW810YQ
SD636VS-EVAL1	TT426YQ	TU409YQ	TU918YQ	TW814YQ
TR730YQ	TT430YQ	TU430YQ	TU922YQ	TW816YQ
TR755YQ	TT435YQ	TU439YQ	TU926YQ	TW818YQ
TT408YQ	TT440YQ	TU455YQ	TU930YQ	TW822YQ
TT409YQ	TU108YQ	TU908YQ	TU935YQ	TW826YQ
TT410YQ	TU127YQ	TU909YQ	TU940YQ	TW830YQ
TT414YQ	TU130YQ	TU910YQ	TW808YQ	TW840YQ

Please plan for the following deadlines:

Last time buy date: **June 30, 2019**

Last time ship date: **December 31, 2019**

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

ESD1908