

Product Name:	538 - FFC / FPC SYSTEMS	
	18pin, 0.4mm pitch Flex connectors	
Product Manager:	Shoichi.Omote	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	End-of-Life	
Change Description:	End of Life of Part number - 10121013-18B10EHLF	
Reason for Change:	After the completion of one of the major projects in 2018, the period of no demand continued for a long time, making it difficult to maintain production facilities.As this item was not produced for last 4 years,there is no stock of the parts and we can't support LTB. This PCN is intended to declare the end of life of this part number. Restarting production has become difficulty due to very low demand.	
Affected Parts:	10121013-18B10EHLF	
Effective Date of Change:	30 June ,2022	
Last Time Buy Date:		
Earliest Disty Return Date:	30 June ,2022	
Last Time Shipment Date		
Datasheet Attached?	No	
Qual/Test Data Attached?	No	
Samples Availability Date:		
Available Alternatives?		
Questions?	<i>Contact your local Amphenol Representative, or Product Manager</i>	
	<i>Shoichi.Omote / Product Manager</i>	
	<i>Shoichi.Omote@amphenol-fci.com</i>	

Note:

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .