

Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

PDN-IF-1681-2018

| Business Unit | Product Line Code | Type of Change | Action | Date of Issue |
|---------------------------|-------------------|-------------------------|-------------------------------|---------------|
| IF - Interface Components | CK6 | Product Discontinuation | Notify Distributors and Field | 6/1/2018 |

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

Phoenix Contact will discontinue PLC relay modules that utilize SPRING CAGE wire connections. These modules are effectively replaced by PLC relays featuring Phoenix Contact's quality PT push-in connection technology.

The impact of this discontinuation and subsequent migration to the recommended replacement modules is limited to the way wiring is inserted/removed from the relay bases. PLC relays featuring PT push-in connection offer all of the benefits of a traditional spring cage terminal – assured torque and fast wiring – without the need to open the wire cage to insert wires. Ferruled or solid wires can be inserted directly into the wire cage of PT push-in connectors without tools, saving even more installation time.

The recommended replacement relays are otherwise equivalent. Featuring identical accessories, technical ratings, wire gauge ranges, and form-factors, PLC relay modules with PT push-in connection can be used as drop-in replacements for PLC relay modules with spring cage connection.

Stock Status

Can existing stock still be used?

Is mixture of stock acceptable?

Transaction Dates

Last Buy from Phoenix Contact: 10/30/2018

Last Scheduled Ship from Phoenix Contact: 4/30/2019



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Clinton Hommel
chommel@phoenixcon.com

Thank you,

Jeremy Valentine

Product Marketing Manager Interface

Product Discontinuation

| Discontinued Part # | Type Description | Replacement Part # | Type Description |
|---------------------|----------------------------|--------------------|---------------------------|
| 2912484 | PLC-BSP-230UC/21-21 | | |
| 2980157 | PLC-OSP- 5DC/ 24DC/ 2/ACT | 2900375 | PLC-OPT- 5DC/ 24DC/2/ACT |
| 2967471 | PLC-OSP- 24DC/ 24DC/ 2 | 2900364 | PLC-OPT- 24DC/ 24DC/2 |
| 2967507 | PLC-OSP- 24DC/ 24DC/ 2/ACT | 2900376 | PLC-OPT- 24DC/ 24DC/2/ACT |
| 2980513 | PLC-OSP- 24DC/ 24DC/ 3RW | 2900379 | PLC-OPT- 24DC/ 24DC/3RW |
| 2982715 | PLC-OSP- 24DC/ 24DC/ 10/R | 2900398 | PLC-OPT- 24DC/ 24DC/10/R |
| 2967549 | PLC-OSP- 24DC/ 48DC/100 | 2900352 | PLC-OPT- 24DC/ 48DC/100 |
| 2980649 | PLC-OSP- 24DC/ 48DC/500/W | 2900378 | PLC-OPT- 24DC/ 48DC/500/W |
| 2982511 | PLC-OSP- 24DC/110DC/ 3RW | 2900391 | PLC-OPT- 24DC/110DC/3RW |
| 2967895 | PLC-OSP- 24DC/230AC/ 1 | 2900369 | PLC-OPT- 24DC/230AC/1 |
| 2980830 | PLC-OSP- 24DC/300DC/ 1 | 2900383 | PLC-OPT- 24DC/300DC/1 |
| 2982524 | PLC-OSP- 36DC/110DC/ 3RW | 2900392 | PLC-OPT- 36DC/110DC/3RW |
| 2982540 | PLC-OSP- 72DC/110DC/ 3RW | 2900394 | PLC-OPT- 72DC/110DC/3RW |
| 2980526 | PLC-OSP-110DC/ 24DC/ 3RW | 2900380 | PLC-OPT-110DC/ 24DC/3RW |
| 2982566 | PLC-OSP-110DC/110DC/ 3RW | 2900396 | PLC-OPT-110DC/110DC/3RW |
| 2967552 | PLC-OSP-120UC/ 48DC/100 | 2900355 | PLC-OPT-120UC/ 48DC/100 |
| 2967497 | PLC-OSP-230UC/ 24DC/ 2 | 2900368 | PLC-OPT-230UC/ 24DC/2 |
| 2967565 | PLC-OSP-230UC/ 48DC/100 | 2900356 | PLC-OPT-230UC/ 48DC/100 |
| 2967934 | PLC-OSP-230UC/230AC/ 1 | 2900374 | PLC-OPT-230UC/230AC/1 |
| 2982676 | PLC-SP-EIK 1-SVN 24/P/P | 2900397 | PLC-PT-EIK 1-SVN 24/P/P |
| 2980254 | PLC-BSP- 5DC/ 1/ACT | 2900448 | PLC-BPT- 5DC/ 1/ACT |
| 2980238 | PLC-BSP- 5DC/21 | 2900443 | PLC-BPT- 5DC/21 |
| 2967426 | PLC-BSP- 12DC/21 | 2900444 | PLC-BPT- 12DC/21 |
| 2912426 | PLC-BSP- 12DC/21-21 | 2900282 | PLC-BPT- 12DC/21-21 |
| 2912332 | PLC-BSP- 12DC/21HC | 2900253 | PLC-BPT- 12DC/21HC |
| 2967196 | PLC-BSP- 24DC/ 1/ACT | 2900449 | PLC-BPT- 24DC/ 1/ACT |
| 2912400 | PLC-BSP- 24DC/ 11C/ACT | 2900260 | PLC-BPT- 24DC/ 11C/ACT |
| 2967219 | PLC-BSP- 24DC/21 | 2900445 | PLC-BPT- 24DC/21 |
| 2912439 | PLC-BSP- 24DC/21-21 | 2900283 | PLC-BPT- 24DC/21-21 |
| 2912345 | PLC-BSP- 24DC/21HC | 2900254 | PLC-BPT- 24DC/21HC |
| 2961396 | PLC-BSP- 24DC/21RW | 2900261 | PLC-BPT- 24DC/21RW |
| 2982809 | PLC-BSP- 24UC/ 1/ACT | 2900450 | PLC-BPT- 24UC/ 1/ACT |
| 2967222 | PLC-BSP- 24UC/21 | 2900446 | PLC-BPT- 24UC/21 |
| 2967167 | PLC-BSP-120UC/21 | 2900280 | PLC-BPT-120UC/21 |
| 2912471 | PLC-BSP-120UC/21-21 | 2900287 | PLC-BPT-120UC/21-21 |
| 2980351 | PLC-BSP-120UC/21/SO46 | 2900453 | PLC-BPT-120UC/21/SO46 |
| 2980380 | PLC-BSP-230UC/ 1/SEN/SO46 | 2900457 | PLC-BPT-230UC/ 1/SEN/SO46 |
| 2967183 | PLC-BSP-230UC/21 | 2900281 | PLC-BPT-230UC/21 |
| 2982692 | PLC-BSP-TTL/1 | 2900458 | PLC-BPT-TTL/1 |
| 2967439 | PLC-RSP- 12DC/21 | 2900316 | PLC-RPT- 12DC/21 |
| 2912497 | PLC-RSP- 12DC/21-21 | 2900329 | PLC-RPT- 12DC/21-21 |
| 2967442 | PLC-RSP- 12DC/21AU | 2900337 | PLC-RPT- 12DC/21-21AU |
| 2967345 | PLC-RSP- 24DC/ 1/ACT | 2900312 | PLC-RPT- 24DC/ 1/ACT |
| 2912413 | PLC-RSP- 24DC/ 11C/ACT | 2900298 | PLC-RPT- 24DC/ 11C/ACT |
| 2966472 | PLC-RSP- 24DC/21 | 2900299 | PLC-RPT- 24DC/21 |
| 2912507 | PLC-RSP- 24DC/21-21 | 2900330 | PLC-RPT- 24DC/21-21 |
| 2912578 | PLC-RSP- 24DC/21-21AU | 2900338 | PLC-RPT- 24DC/21-21AU |
| 2966540 | PLC-RSP- 24DC/21AU | 2900306 | PLC-RPT- 24DC/21AU |
| 2912277 | PLC-RSP- 24DC/21HC | 2900291 | PLC-RPT- 24DC/21HC |
| 2966485 | PLC-RSP- 24UC/21 | 2900300 | PLC-RPT- 24UC/21 |



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

| | | | |
|---------|---------------------------|---------|---------------------------|
| 2912510 | PLC-RSP- 24UC/21-21 | 2900332 | PLC-RPT- 24UC/21-21 |
| 2987105 | PLC-RSP- 24UC/21-21/RW | 2900346 | PLC-RPT- 24UC/21-21/RW |
| 2912581 | PLC-RSP- 24UC/21-21AU | 2900339 | PLC-RPT- 24UC/21-21AU |
| 2987011 | PLC-RSP- 24UC/21/RW | 2900318 | PLC-RPT- 24UC/21/RW |
| 2966553 | PLC-RSP- 24UC/21AU | 2900307 | PLC-RPT- 24UC/21AU |
| 2987024 | PLC-RSP- 24UC/21AU/RW | 2900321 | PLC-RPT- 24UC/21AU/RW |
| 2987079 | PLC-RSP- 24UC/21HC/RW | 2900324 | PLC-RPT- 24UC/21HC/RW |
| 2987121 | PLC-RSP- 72UC/21-21/RW | 2900347 | PLC-RPT- 72UC/21-21/RW |
| 2987037 | PLC-RSP- 72UC/21/RW | 2900319 | PLC-RPT- 72UC/21/RW |
| 2987040 | PLC-RSP- 72UC/21AU/RW | 2900322 | PLC-RPT- 72UC/21AU/RW |
| 2966524 | PLC-RSP-120UC/21 | 2900304 | PLC-RPT-120UC/21 |
| 2912549 | PLC-RSP-120UC/21-21 | 2900335 | PLC-RPT-120UC/21-21 |
| 2966582 | PLC-RSP-120UC/21AU | 2900310 | PLC-RPT-120UC/21AU |
| 2966537 | PLC-RSP-230UC/21 | 2900305 | PLC-RPT-230UC/21 |
| 2912552 | PLC-RSP-230UC/21-21 | 2900336 | PLC-RPT-230UC/21-21 |
| 2966647 | PLC-RSP-230UC/21AU | 2900311 | PLC-RPT-230UC/21AU |
| 2912329 | PLC-RSP-230UC/21HC | 2900297 | PLC-RPT-230UC/21HC |
| 2987312 | PLC-2RSP-24DC/ 1 | 2901639 | PLC-2RPT-24DC/1 |
| 2968001 | PLC-RSP-230UC/21-21AU/RWF | 2900345 | PLC-RPT-230UC/21-21AU/RWF |
| 2980555 | PLC-SP-ELR W1/ 2-24DC | | |