

Product Discontinuation

2006-10-04

OS-PD-2006-008

Last order:	15.04.2007
Last delivery:	15.10.2007

Reason: Low demand

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
LK A W01	Q65110A2929	LED	Eng. Kit	No replacement			
LK B W01	Q65110A2927	LED	Eng. Kit	No replacement			
LK CW W01	Q65110A2926	LED	Eng. Kit	No replacement			
LK MIX W01	Q65110A2925	LED	Eng. Kit	No replacement			
LK T W01	Q65110A2924	LED	Eng. Kit	No replacement			
LK V W01	Q65110A2923	LED	Eng. Kit	No replacement			
LK W W01	Q65110A2922	LED	Eng. Kit	No replacement			
LK Y W01	Q65110A2921	LED	Eng. Kit	No replacement			
LK ACC W01	Q65110A2928	LED	Eng. Kit	No replacement			