

**Type of Notification:****To:** Sales

- |   |  |                                     |
|---|--|-------------------------------------|
| <input type="checkbox"/> Product Change | <input type="checkbox"/> Process Change          | <input type="checkbox"/> Relocation |
| <input type="checkbox"/> Product Alert  | <input checked="" type="checkbox"/> Obsolescence | <input type="checkbox"/> Other      |

**Notification Date:** August 30, 2015**Effective Date:** September 30, 2015AVX Part Number / Series / Product: 009178001001006 & 009178001002006Customer Part Number / Series / Drawing: N/AMaterial Identification: N/ADate Code / Lot Code: N/A**Applicable Information for Product Alerts:**

Purchase Order Number: _____	Shipment Date: _____
Packing Slip Number(s): _____	Quantity: _____

**Description of Advisory / Notice:**

The tooling which produces the above IDC Coax connectors is worn and current volumes and business level does not justify spending the money to invest in new tooling. AVX will accept and attempt to produce any last time buy quantities for as long as the tooling remains operational. Please submit any last time buy orders prior to September 30, 2015.

**Point of Contact:**

<b>Name:</b>	<b>Tom Anderson</b>	<b>Title:</b>	<b>Product Manager</b>
<b>Address:</b>	<b>AVX Corporation</b>	<b>Telephone #:</b>	<b>864-228-3421</b>
	<b>1 AVX Boulevard</b>	<b>Fax #:</b>	
	<b>Fountain Inn, SC 29644</b>	<b>E-Mail:</b>	<b>Tom.Anderson@avx.com</b>