


Light is OSRAM

Product Or Individual Q-Code Discontinuation (acc. JEDEC J-STD-048) OS-PDN-2021-051

04 May 2021

Last order:	04 May 2022
Last delivery:	04 November 2022



Please direct your feedback to your local Sales office.

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
SFH 3600-Z	Q65110A1573	MIDLED	material discontinuation	SFH 3219	Q62702P5551	TOPLED
SFH 3600-3/4-Z	Q65110A2666	MIDLED	material discontinuation	SFH 3219	Q62702P5551	TOPLED
SFH 3600-3-Z-XX	Q65113A0241	MIDLED	material discontinuation	SFH 3219	Q62702P5551	TOPLED
SFH 3605-Z	Q65110A1574	MIDLED	material discontinuation	SFH 3015 FA	Q65110A9730	CHIPLED
SFH 3605-3/4-Z	Q65110A2664	MIDLED	material discontinuation	SFH 3015 FA	Q65110A9730	CHIPLED
SFH 4140	Q65111A4190	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4140-U-XX	Q65111A7460	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4441	Q65111A4266	MIDLED	material discontinuation	SFH 4248	Q65110A3304	Power TOPLED
SFH 4441-V-XX	Q65112A1832	MIDLED	material discontinuation	SFH 4248	Q65110A3304	Power TOPLED
SFH 4441 E9613	Q65112A5158	MIDLED	material discontinuation	SFH 4248	Q65110A3304	Power TOPLED
SFH 4441 E9621	Q65112A8137	MIDLED	material discontinuation	SFH 4248	Q65110A3304	Power TOPLED
SFH 4451	Q65111A2583	MIDLED	material discontinuation	SFH 4258	Q65110A2976	Power TOPLED
SFH 4451-UV	Q65111A4223	MIDLED	material discontinuation	SFH 4258	Q65110A2976	Power TOPLED
SFH 4451-V	Q65111A6962	MIDLED	material discontinuation	SFH 4258	Q65110A2976	Power TOPLED
SFH 4640	Q65110A9369	MIDLED	material discontinuation	SFH 4248	Q65110A3304	Power TOPLED
SFH 4640-UV	Q65111A3977	MIDLED	material discontinuation	SFH 4248	Q65110A3304	Power TOPLED
SFH 4640-VAW	Q65112A9418	MIDLED	material discontinuation	SFH 4248	Q65110A3304	Power TOPLED
SFH 4640-V	Q65113A2226	MIDLED	material discontinuation	SFH 4248	Q65110A3304	Power TOPLED
SFH 4641-Z	Q65110A8098	MIDLED	material discontinuation	SFH 4544	Q65111A4886	Radial
SFH 4641-UV	Q65111A4669	MIDLED	material discontinuation	SFH 4544	Q65111A4886	Radial

DISCONTINUED				NEW (REPLACEMENT)		
Device	Ordering Code	Brand	Reason for discontinuation	Device	Datasheet Ordering Code	Brand
SFH 4641-T1V	Q65111A5899	MIDLED	material discontinuation	SFH 4544	Q65111A4886	Radial
SFH 4641-U-XX	Q65111A6466	MIDLED	material discontinuation	SFH 4544	Q65111A4886	Radial
SFH 4645	Q65110A9367	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4645-UV-Z	Q65110A9606	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4645-V	Q65111A5761	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4646-Z	Q65110A8099	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4646-T2V	Q65111A0354	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4646-TV	Q65111A6148	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4646-UV	Q65111A8253	MIDLED	material discontinuation	SFH 4045N	Q65111A3903	CHIPLED
SFH 4650-Z	Q65110A1572	MIDLED	material discontinuation	SFH 4059S	Q65111A0278	CHIPLED
SFH 4650-UV-Z	Q65110A7888	MIDLED	material discontinuation	SFH 4059S	Q65111A0278	CHIPLED
SFH 4650-UV R33-Z	Q65110A9784	MIDLED	material discontinuation	SFH 4059S	Q65111A0278	CHIPLED
SFH 4650-VAW	Q65112A8148	MIDLED	material discontinuation	SFH 4059S	Q65111A0278	CHIPLED
SFH 4651-Z	Q65110A8396	MIDLED	material discontinuation	SFH 4059	Q65111A2991	CHIPLED
SFH 4651-U	Q65111A0425	MIDLED	material discontinuation	SFH 4059	Q65111A2991	CHIPLED
SFH 4651-UV	Q65111A4394	MIDLED	material discontinuation	SFH 4059	Q65111A2991	CHIPLED
SFH 4655-Z	Q65110A1569	MIDLED	material discontinuation	SFH 4350	Q65110A2091	Radial
SFH 4655-UV	Q65111A3814	MIDLED	material discontinuation	SFH 4350	Q65110A2091	Radial
SFH 4655-VAW	Q65112A6723	MIDLED	material discontinuation	SFH 4350	Q65110A2091	Radial
SFH 4656-Z	Q65110A8395	MIDLED	material discontinuation	SFH 4551	Q65111A0506	Radial