

Product Notification Form

PCN #: PCN17-0022.docx	Rev: 1.0	Issue Date: May 01 st , 2017						
Type of Change: Product Notification for a firmware improvement in the Series U-45 USB Modules <input checked="" type="checkbox"/> minor / <input type="checkbox"/> major								
Detailed Description of Change: <ul style="list-style-type: none"> - Fix an issue that could result in a permanent write protected (read-only) state of the card. This situation can be triggered by a specific write command sequence and timing only. <p>The new firmware can be updated in the field with a software tool. The firmware update tool (incl. instruction manual) can be downloaded here: ftp://public:public@office.swissbit.com/SFxx_FwUpdate/SBUpdate-U-45_U-46_160707_1.11.zip</p>								
Quality impact: <input type="checkbox"/> minor / <input type="checkbox"/> major / <input checked="" type="checkbox"/> no								
Reliability impact: <input checked="" type="checkbox"/> minor / <input type="checkbox"/> major / <input type="checkbox"/> no								
Products affected: <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 5px;"> <thead> <tr> <th style="width: 33%;">Series</th> <th style="width: 33%;">Part Number</th> <th style="width: 33%;">New Part Number</th> </tr> </thead> <tbody> <tr> <td>U-45 USB Modules</td> <td>SFUIxxxxxy1ABxT0-t-xx-2A1-STD</td> <td>Same, no change</td> </tr> </tbody> </table> <p>t = temperature grade C or I; y = 2.00mm or 2.54mm pitch (K / J) ; x = density, options and custom configuration</p>			Series	Part Number	New Part Number	U-45 USB Modules	SFUIxxxxxy1ABxT0-t-xx-2A1-STD	Same, no change
Series	Part Number	New Part Number						
U-45 USB Modules	SFUIxxxxxy1ABxT0-t-xx-2A1-STD	Same, no change						
Implementation date: Shipments starting from May 02, 2017								
Recommended action: Update to the new firmware with an available software update tool or contact our RMA department to arrange the exchange: rma-pool@swissbit.com .								
<p>Should you have any questions or concerns with the content of this change, please contact the Swissbit PCN team at customer.pcn@swissbit.com within 30 days. No response will be deemed as customer's acceptance of the change and the change will be implemented pursuant to the implementation date set forth in this PCN.</p> <p style="text-align: center;">IMPORTANT NOTE: <i>Swissbit – as a provider of industrial products – announces and informs about every change in the product hardware and firmware. We always test backwards compatibility and assure best quality, reliability and transparency for our customers. We apologize for any inconvenience caused.</i></p>								

Product Notification Form

Affected products:

PN	Description
606077	SFUI4096K1AB1T0-I-GS-2A1-STD
606076	SFUI4096K1AB1T0-C-GS-2A1-STD
605754	SFUI4096J1AB1T0-I-GS-2A1-STD
605755	SFUI4096J1AB1T0-C-GS-2A1-STD
605757	SFUI8192K1AB1T0-I-GS-2A1-STD
605758	SFUI8192K1AB1T0-C-GS-2A1-STD
605256	SFUI8192J1AB1T0-I-GS-2A1-STD
605756	SFUI8192J1AB1T0-C-GS-2A1-STD
605761	SFUI016GK1AB1T0-I-GS-2A1-STD
605762	SFUI016GK1AB1T0-C-GS-2A1-STD
605248	SFUI016GJ1AB1T0-I-GS-2A1-STD
605760	SFUI016GJ1AB1T0-C-GS-2A1-STD
605707	SFUI032GK1AB2T0-I-GS-2A1-STD
605708	SFUI032GK1AB2T0-C-GS-2A1-STD
605709	SFUI032GJ1AB2T0-I-GS-2A1-STD
605710	SFUI032GJ1AB2T0-C-GS-2A1-STD