



Product Change Notification

TE Connectivity

Product Change Notification: P-20-018882

PCN Date: 06-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Notification of packaging changes for -STK tubing products.

Description of Changes

This is a notification informing TE Connectivity customers that the packaging boxes used for the tubing -STK products will be changing.

Other attachments:

[Stick parts for Box changes 0232](#)

[New Stick Boxes 2020](#)

[PCN - Changes to -STK boxes](#)

Reason for Changes:

Product improvement. We are moving to a more robust design that will give better protection to the tubing products during transportation. The boxes are moving from a square profile to a rectangular one with different cardboard and latching method. We will be transitioning boxes as existing packaging is consumed so not all product will change at the same time.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	08-APR-2020

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-OCT-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
0879832001	NO			"1190648-8", "RPPM-16/4-X-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5509112121	NO			"7-1194351-0", "ATUM-24/8-0-MS-STK"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
6645972005	NO			"9-1195236-8", "ZH-100-3/4-0-STK"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CB03242002	NO			"TSAS-UNSLIT-NR502-X-STK", "5-1899314-6"			
CH00902001	NO			"TSAS-UNSLIT-NR501-X-STK", "1899279-8"			
CV25332001	NO			"RW-175-E-1/8-X-STK", "5-1899810-5"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CV25902001	NO			"RW-175-E-1/2-X-STK", "4-1899810-8"			
EG85432001	NO			"RBK-VWS-125-NR1-X-STK", "7-1899833-2"			
NB07752001	NO						
NB08082001	NO						
NB08192001	NO						
NB09282001	NO						
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10572001	NO						
NB10802001	NO						
NB10892001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11382001	NO						
NB11622001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11802001	NO						
NB12042001	NO						
NB12762001	NO						
NB13052001	NO						
NB13542001	NO						
NB13892001	NO						
NB14032001	NO						
NB14062001	NO						
NB14832001	NO						
NB14882001	NO						
NB14902001	NO						
NB14932001	NO						
NB16352001	NO						
NB16502001	NO						
NB17042001	NO						
NB17632001	NO						
NB17662001	NO						
NB17872001	NO						
NB17902001	NO						
NB18302001	NO						
NB18792001	NO						
NB18932001	NO						
NB19162001	NO						
NB19642001	NO						
NB25752001	NO						
NB25842001	NO						
NB25902001	NO						
NB25962001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5509112121	NO			"7-1194351-0", "ATUM-24/8-0-MS-STK"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
6645972005	NO			"9-1195236-8", "ZH-100-3/4-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB09282001	NO						
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10572001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11382001	NO						
NB11622001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11802001	NO						
NB12042001	NO						
NB12762001	NO						
NB13052001	NO						
NB13542001	NO						
NB13892001	NO						
NB14032001	NO						
NB14062001	NO						
NB14832001	NO						
NB14882001	NO						
NB14902001	NO						
NB14932001	NO						
NB16352001	NO						
NB16502001	NO						
NB17632001	NO						
NB18302001	NO						
NB18792001	NO						
NB18932001	NO						
NB19162001	NO						
NB19642001	NO						
NB25842001	NO						
NB25962001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
6645972005	NO			"9-1195236-8", "ZH-100-3/4-0-STK"			
CV25332001	NO			"RW-175-E-1/8-X-STK", "5-1899810-5"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11382001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11802001	NO						
NB12042001	NO						
NB13892001	NO						
NB14032001	NO						
NB14062001	NO						
NB14832001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
0879832001	NO			"1190648-8", "RPPM-16/4-X-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CB03242002	NO			"TSAS-UNSLIT-NR502-X-STK", "5-1899314-6"			
CV25332001	NO			"RW-175-E-1/8-X-STK", "5-1899810-5"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
EG85432001	NO			"RBK-VWS-125-NR1-X-STK", "7-1899833-2"			
NB07752001	NO						
NB08082001	NO						
NB08192001	NO						
NB10132001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
0879832001	NO			"1190648-8", "RPPM-16/4-X-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CB03242002	NO			"TSAS-UNSLIT-NR502-X-STK", "5-1899314-6"			
CH00902001	NO			"TSAS-UNSLIT-NR501-X-STK", "1899279-8"			
CV25332001	NO			"RW-175-E-1/8-X-STK", "5-1899810-5"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
CV25902001	NO			"RW-175-E-1/2-X-STK", "4-1899810-8"			
EG85432001	NO			"RBK-VWS-125-NR1-X-STK", "7-1899833-2"			
NB07752001	NO						
NB08082001	NO						
NB08192001	NO						
NB10132001	NO						
NB10892001	NO						
NB17042001	NO						
NB17662001	NO						
NB17872001	NO						
NB17902001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB25752001	NO						
NB25902001	NO						