



5245 Hellyer Avenue  
 San Jose, CA 95138  
 U.S.A.  
 (408) 414-9200

Control No. PCN-17242

July 17, 2017

**PRODUCT DISCONTINUATION NOTICE**

**TYPE OF CHANGE:**       Design                       Manufacturing                       **Other: Obsolescence**

Product discontinuation signifies the final stage of the product life cycle. It is Power Integrations’ policy to provide sufficient notice to customers to allow re-design with replacement parts and/or place final orders. All such orders will be non-cancellable and non-returnable. Please contact your local Power Integrations sales office to arrange final orders for the affected product(s).

**DESCRIPTION:**

Manufacture of TOP253PNAU and TOP267VGAU has been replaced by TOP253PN and TOP267VG respectively.

**REASON FOR DISCONTINUANCE:**

Migration from the gold bond wire to copper bond wire.

**ALTERNATE PARTS:**

The replacement products are identical to the existing products with the exception of the bond wire. There is no adverse impact is expected in the manufacturer’s applications. The replacement products are guaranteed to meet the datasheet limits.

Existing Part Number	Replacement Part Number
TOP253PNAU	TOP253PN
TOP267VGAU	TOP267VG

**DISCONTINUATION SCHEDULE:**

The last time buy order schedule is as follows:

**LAST ORDER DEADLINE:** July 17, 2018

**FINAL SHIPMENT DATE:** July 17, 2019

Please contact your local PI sales office for samples to help migration to the replacement product.

**CONFIDENTIAL**

The information in this report contains confidential and proprietary information of Power Integrations and its manufacturing partners. By receiving this report, the customer agrees to use this information for the sole purpose of addressing the issues reviewed in this report and to keep the contents confidential. If it becomes necessary for the customer to disclose this information to a third party, a non-disclosure agreement, which provides reasonable and customary protection for the disclosed information, must be executed.