

**1 Products affected**

Product hierarchy no. *				Part no.	SBU	Type / Description
SBU	PG	PUG	Type	See list below	Circuit Protection	172322
01	001	022	0000000072			

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)



List of part numbers affected				
7010.7030.13	7010.7030.37	7010.7030.39	7010.7030.47	7010.7030.49
7010.7040.13	7010.7040.37	7010.7040.39	7010.7040.47	7010.7040.49
7010.7050.13	7010.7050.37	7010.7050.39	7010.7050.47	7010.7050.49
7010.7060.13	7010.7060.37	7010.7060.39	7010.7060.47	7010.7060.49
7010.7070.13	7010.7070.37	7010.7070.39	7010.7070.47	7010.7070.49
7010.7080.13	7010.7080.37	7010.7080.39	7010.7080.47	7010.7080.49
7010.7090.13	7010.7090.37	7010.7090.39	7010.7090.47	7010.7090.49
7010.7100.13	7010.7100.37	7010.7100.39	7010.7100.47	7010.7100.49
7010.7110.13	7010.7110.37	7010.7110.39	7010.7110.47	7010.7110.49
7010.7180.13	7010.7180.37	7010.7180.39	7010.7180.47	7010.7180.49
7010.7120.13	7010.7120.37	7010.7120.39	7010.7120.47	7010.7120.49

**2 Type of change**

- Change of approval

**3 Detailed description of change**

The affected part numbers no longer have a 125 VDC rating from UL.

Old Breaking Capacity Rating	New Breaking Capacity Rating
 50A @ 125 VAC 300A @ 125 VDC	 UL 50A @ 125 VAC

**4 Reason of change**

Adaption of new UL approval instruction.

**5 Release date**

The change will be rolled-out starting ww 35/2018 (Date code 1835 or higher on label).

**6 Impact of change and recommended action**

	Impact on application	Recommended action
Form	No	No
Fit	No	No
Function	Yes	Check if this Breaking Rating is mandatory in your application
Manufacturing	No	No
Label	No	No
Packaging	No	No

**7 Reference Documents / Attachments**

Kind of document	Remarks
<a href="#">172322 Datasheet</a>	

Product Change Notification					939 PCN-172322		
owner	creation date	release date	released by	change order no	rev	page	D10-028-940
schmidre	24.08.2018	24.08.2018	haeckima	2016129	A	1 of 1	