



Product Change Notification

TE Connectivity

Product Change Notification: E-21-000311

PCN Date: 11-JAN-21

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
DEUTSCH DT Metal Mounting Clips, Adding Second Supplier

Description of Changes
The Industrial and Commercial Transportation business unit of TE Connectivity is adding a supplier for the following part numbers located in China. These PNs are TE proprietary designs, therefore considered catalog/general market product. TE reserves the right to use both locations/suppliers based on business needs. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason for Changes:
Dear Customer, we hereby inform you of this change. This change is necessary to supply the China region. The change will not impact connector performance. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

| Estimated Dates: | |
|--|--|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 15-MAR-2021 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 15-SEP-2022 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1027-003-1200 | NO | | | "ZPF000000000139328" | | | |
| 1027-004-1200 | NO | | | "ZPF000000000131774" | | | |
| 1027-008-1200 | NO | | | | | | |
| 1027-017-1200 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1027-003-1200 | NO | | | "ZPF000000000139328" | | | |
| 1027-004-1200 | NO | | | "ZPF000000000131774" | | | |
| 1027-008-1200 | NO | | | | | | |
| 1027-017-1200 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1027-003-1200 | NO | | | "ZPF00000000139328 | | | |
| 1027-004-1200 | NO | | | "ZPF00000000131774 | | | |
| 1027-008-1200 | NO | | | | | | |
| 1027-017-1200 | NO | | | | | | |