



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000966I

DATE: 03-Apr-2019

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS28E05X+U	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX1086C/D+C01063	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAXQ1010-A01+	N/A			Part reactivated from prior notice: M000886
Discontinuance	806-0472-90-A4	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	806-0508-90-A4	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	806-0523-90-A4	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	806-0567-90-A4	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	MAX9132GUP/V+	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	MAX9132GUP/V+T	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	MAX9134GHJ+T	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	MAX9135GHJ+T	N/A	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured
Discontinuance	MAX9288GGM+	MAX9288GGM/VY+	03-Apr-2019	03-Apr-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 04-May-2019