



Product Change Notification / JAON-10JJSR230

Date:

16-Mar-2021

Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

PCN Type:

End of Life

Notification Subject:

eSign# E000044621: End of Life (EOL) of DSPIC33FJ16GS504-50I/TL catalog part number (CPN).

Affected CPNs:

[JAON-10JJSR230_Affected_CPN_03162021.pdf](#)

[JAON-10JJSR230_Affected_CPN_03162021.csv](#)

Notification Text:

PCN Status: End of Life (EOL) notification

Microchip Parts Affected: Please open one of the files found in the Affected CPNs section.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field labeled as PCN_#_Affected_CPN.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description: The DSPIC33FJ16GS504-50I/TL catalog part number (CPN) will be moving to End of Life (EOL) status effective today. This product will no longer be offered after March 16, 2021. Please review the attached parts affected list for details about replacement parts if applicable.

If replacement parts are not listed in the attached list, please contact your **Local Sales Representative** for alternative packages in the same part family.

Reason for EOL: No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates: March 16, 2021

Revision History: March 16, 2021: Issued the EOL notification.

Attachments:

[PCN_JAON-10JJSR230_Affected_CPN.pdf](#)

[PCN_JAON-10JJSR230_Affected_CPN.xlsx](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

DSPIC33FJ16GS504-50I/TL