

Date: March 26, 2018

PCN- 28016

Product Change Notification

Change Title:

CADMIUM PLATED U-CLAMP OBSOLETE

Product (s) Affected:

480Z, P2381, 2P1818

Reason for Change:

CADMIUM PLATE SUPPLIERS ARE VANISHING AND/OR NO LONGER AVAILABLE.

Description of Change:

OBSOLETE 480Z - REPLACE WITH 480X (U-CLAMP IS DULL TIN PLATED)

OBSOLETE P2381 - REPLACE WITH P2381X (U-CLAMP IS DULL TIN PLATED)

OBSOLETE 2P1818 - NO REPLACEMENT.

Estimated Schedule of Change:

IMMEDIATE

Customer Acknowledgement Form

(To be filled out by the customer and returned to Switchcraft)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: _____

Signature

(Electronic Signature is acceptable)

Print

Company: _____

Location: _____

Title: _____

Date: _____

Please return the signed PCN form to the attention of:

Switchcraft Customer Service Department

jpulliam@switchcraft.com

FAX: 773-792-2129