



Product Change Notification

TE Connectivity

Product Change Notification: E-19-018370

PCN Date: 26-NOV-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMP MCP 1.5K PRODUCT GROUP DRAWING

Description of Changes

Please be informed that as part of the AMP MCP optimization program done in 2011 to improve the performance with regards to Slow Motion bending test and LV 214 qualification the following PNs are superseded: 1241372-1 superseded with PN 1564980-1, 1241372-2 superseded with PN 1564980-2, 1241378-1 superseded with PN 1564324-1, 1241378-2 superseded with PN 1564324-2 and 1241378-3 superseded with PN 1564324-3) Please also see earlier PCN P-18-016232.

Other attachments:

[E-19-018370](#)

Reason for Changes:

Discontinuance. Discontinuance. Discontinuance - Superseded PNs, Part status change

Estimated Dates:

Last Order Date (Obsolete Parts Only):

02-MAR-2020

First Date To Ship (Changed Parts Only):

Last Ship Date (Obsolete Parts Only):

09-MAR-2020

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1241378-1	YES				1564324-1		Crimp optimized
1241378-1	YES				1564324-1		Crimp optimized

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
1241436	1241378-1		B22	

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1241378-1	YES				1564324-1		Crimp optimized

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1241378-1	YES				1564324-1		Crimp optimized

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
1241436	1241378-1		B22	