

Product Discontinuation

PDN-ION-4068-2019

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ION - I/O and Networks	DNN	Product Discontinuation	Notify Distributors and Field	7/24/2019

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

Due to component discontinuation, the FL HUB series has been discontinued

Stock Status

Can existing stock still be used?

Is mixture of stock acceptable?

Transaction Dates

Last Buy from Phoenix Contact: 5/31/2019

Last Scheduled Ship from Phoenix Contact: 11/30/2019

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Ken Austin
kaustin@phoenixcontact.com

Thank you,

Dan Schaffer

Prod Mkt Mgr Indust Ntwk



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
2832564	FL HUB 16TX-ZF		
2832551	FL HUB 8TX-ZF		