



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631 www.littelfuse.com

June 25th, 2020

RE: Obsolescence of DRS-50 Series Reed Switches

To our valued customers,

Littelfuse would like to notify you that we are obsoleting the DRS-50 series reed switches. There is no suggested replacement. Please refer to below affected material part numbers

All existing orders in the system will still be served.

The last time buy will be on Sept 30th 2020.

Thank you, for your attention on this matter.

Best Regards,

Crispin Zulueta
Assistant Product Manager - Sensors
Electronics Business Unit
Littelfuse Inc.

Max Shi
Product Manager – Sensors
Electronics Business Unit
Littelfuse Inc.

Julius Venckus
Global Product Manager – Sensors
Electronics Business Unit
Littelfuse Inc.

RS Materials for OB	
DRS-50-42-48	DRS-50-87-93



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631 www.littelfuse.com

DRS-50-42-53	DRS-50-92-98
DRS-50-42-83	DRS-50-97-103
DRS-50-47-53	DRS-50-Q1429
DRS-50-47-63	DRS-50-Q1796-1
DRS-50-47-68	DRS-50-Q1797
DRS-50-52-58	DRS-50-Q1919
DRS-50-52-63	DRS-50-Q1986-4
DRS-50-52-73	DRS-50-Q2335
DRS-50-57-63	DRS-50-Q2540-2
DRS-50-57-68	DRS-50-Q362-2
DRS-50-62-68	DRS-50-Q4163
DRS-50-62-73	DRS-50-Q448-12
DRS-50-62-78	DRS-50-Q551
DRS-50-62-83	DRS-50-Q695-1
DRS-50-67-73	DRS-50-Q696-6
DRS-50-72-78	DRS-50-Q4603
DRS-50-72-83	DRS-50-82-88
DRS-50-77-83	DRS-50-82-93
DRS-50-77-88	DRS-50-82-93- SYM

Sensors: Material PN for OB

59130-507

59130-500