



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000819I

DATE: 14-Oct-2014

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	DS1848B-C10/T&R	N/A	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS1848B-C50/T&R	N/A	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS1855B-100	N/A	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS1856B-M50	DS1856B-M50+	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	DS1856B-M50/T&R	DS1856B-M50+T&R	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331AUK/GG8	MAX9647AUK+T	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331AUK/GH9	MAX9647AUK+T	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX331AUK/GH9-T	MAX9647AUK+T	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX3205EABL/GG8	N/A	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX3299CUE	MAX3735AETG+T	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX3299CUE-T	MAX3735AETG+T	14-Oct-2014	13-Oct-2016	Part is leaded. Request information on lead-free version
Discontinuance	5962-8759101LA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8776302LA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8876401LA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8876701LA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8876702LA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8965702LA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8987705JA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8987706JA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8987707JA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	5962-8987708JA	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	DS1845X-010/T&R	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1845X-050/T&R	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1845X-100/T&R	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1848B-C10+T&R	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	DS1848B-C50+T&R	N/A	14-Oct-2014	13-Oct-2016	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Nov-2014

Discontinuance	DS1854B-050	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1854E-050	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1855B-020	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1855B-050+	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1855B-100+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	DS1857B-050	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1857B-050+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	DS2434S/T&R/	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	ICL7631BMJE/M60098	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX15202ETE+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX15302ETL+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX15302ETL+T	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX15304ETJ+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX15304ETJ+T	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX154AMRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX154BMRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX164BMRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX164CMRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX172AMRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX172BMRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX191AMRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX191BMRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX236MRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX237MRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX238MRG/HR	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX239MRG/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX24000-EVAL-OA	N/A	14-Oct-2014	13-Oct-2016	EVKIT is No Longer Supported
Discontinuance	MAX24000TL+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX24000TL+T	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX24001TL+W	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX24002TL+W	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX24003TL+TW	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX24023ETJ+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX323MSA/R30437	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3261CCJ+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX3261ECJ+	N/A	14-Oct-2014	13-Oct-2016	The part was not released

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Nov-2014**

Discontinuance	MAX3289CUE	MAX3735AETG+T	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3668E/D	MAX3735AETG+T	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3761E/D	MAX3748HETE+	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3762E/D	MAX3748HETE+	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX3869E/D	MAX3735AETG+T	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3934BE/D-B50101	MAX3949ETE+	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3945AETE+T	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX3947E/D+	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3957ETL+	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX3964AC/D-B50107	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX516AML/M40197	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX632AMJA/HR	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX663MJA/HR	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MAX690AMSA/PR-W	N/A	14-Oct-2014	13-Oct-2016	The part was not released
Discontinuance	MX7228TQ/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7545UQ/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7547SQ/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7547TQ/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7547UQ/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7572SQ05/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7572SQ12/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7824TQ/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7824UQ/883B	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	PHY2065-01QS-BR	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured
Discontinuance	PHY2065-01QS-RR	N/A	14-Oct-2014	13-Oct-2016	Part can no longer be manufactured