

SOURIAU

25 Grumbacher Road
York, Pa 17406
USA

Tel.: +1 (717) 767 6705
Fax: +1 (717) 505 5945
www.souriau.com

June 11, 2014

Dear Valued Customer

Souriau USA Inc. is sending this notice to inform you of the end of life for M10S-1J hand tool and associated dies used on Trim Trio contacts.

Product Part Numbers:

| | | | | |
|---------|-------|--------|--------|--------|
| M10S-1J | S-7 | S55 | SL-33 | SL59 |
| M10SG8 | S-8 | S61 | SL-39 | SL64 |
| M10SK-2 | S-80 | S67 | SL-3A | SL66-1 |
| M10SK-3 | S-83 | S68 | SL-4 | SL67 |
| S-1 | S-87 | S70 | SL-40 | SL68 |
| S-10 | S-88 | S71 | SL-53 | SL69 |
| S-16 | S-9 | S79 | SL-58 | SL70 |
| S-23D2 | S20 | S7D1 | SL-74 | SL71 |
| S-26D2 | S22-1 | S82 | SL106 | SL72 |
| S-28 | S30 | SL-105 | SL110 | SL83 |
| S-29 | S31 | SL-115 | SL114 | SL84 |
| S-33 | S32 | SL-127 | SL128 | SL89 |
| S-35 | S37B | SL-16 | SL27 | SL90 |
| S-3D1 | S41 | SL-19 | SL35 | SL91D2 |
| S-42 | S45 | SL-2 | SL44 | SL92D1 |
| S-44 | S45G1 | SL-21 | SL46-1 | SL93 |
| S-5 | S471 | SL-26 | SL47-1 | SL94 |
| S-6A | S50 | SL-29 | SL49 | SL98 |

Description of Change: M10S-1J crimping tool and all associated parts (Die set and locator) will no longer supported by SOURIAU. All part numbers covered by this notice are written in the table above.

Anticipated Impact on Form, Fit, or Function: N/A. Contacts are not modified. Tools can still be used.

Implementation Date: Immediate, Souriau will accept orders within the next 30 days and will deliver in a maximum period of 6 months.

Souriau offers an existing line of replacement tooling for Trim Trio contacts. If you require crimp tooling support in the future, please contact Technical Support with the contact part number to obtain active tooling part numbers.

Souriau Contact Information: Email: TechnicalSupport@souriau.com / Phone: 717-767-6705

SOURIAU