



Product Change Notification

TE Connectivity

Product Change Notification: E-15-002423

PCN Date: 26-FEB-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
1410187-X Right angle plug assembly, 7 Row, 20.3mm Multigig

Description of Changes
TE production Drawing 1410187-X is missing the arrows pointer at the wafers location in Zones D7 and D8. There have been no changes to the existing parts, this is a revision increase only.

Reason for Changes:
Document Clarification. Software glitched, it caused the TE PD 1410187-X missed the arrows pointer in Zone D7 and D8.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	02-MAR-2015
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	27-MAR-2015

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1410187-1	NO						
1410187-3	NO						