



Product Discontinuance Notice - PDN 18_0085 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Obsolescence of Material Number HMC737LP4E and HMC737LP4ETR

Publication Date: 12-Dec-2018

Last Time Buy Date: 12-Dec-2019

Last Time Ship Date: 12-Dec-2020

Revision Description:

Initial Release

Reason For Discontinuance

Discontinued due to decreased customer demand.

Comments

Recommended replacement: ADF5610 58 MHz - 15 GHz integrated PLLVCO.

There are a number of similar discrete products that can also be used to replace this product. See www.analog.com/vco

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com	Europe: PDN_Europe@analog.com	Japan: PDN_Japan@analog.com
		Rest of Asia: PDN_ROA@analog.com

PDN 18_0085 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
HMC737LP4E	HMC737	See Comments	N/A	ADF5610; similar discrete parts on www.analog.com/vco
HMC737LP4ETR	HMC737	See Comments	N/A	ADF5610; similar discrete parts on www.analog.com/vco

Appendix A - PDN 18_0085 Revision History

Rev	Publish Date	Rev Description
Rev. -	12-Dec-2018	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1332 Layout Rev:2 Parent DocId:None