

Light is OSRAM

26.01.2018

## OS-IN-2018-004 Change of laser marking position for Kx CSLyM.zz


**Objective** Change of laser marking position

**Products affected**  
KP CSLNM1.F1  
KW CSLNM1.TG  
KR CSLNM1.23  
KB CSLNM1.14  
KP CSLPM1.F1  
KW CSLPM1.TG

**Background** Harmonization of the laser mark position to improve visual inspection capability.

**Realization**

Current:



New:



**Time Schedule** CW03/2018. Datasheets will be updated at the beginning of february.

**Please direct your inquiry to your local Sales office.**

OSRAM Opto Semiconductors  
GmbH

Head Office:

Leibnizstrasse 4  
93055 Regensburg, Germany  
Phone +49 941 850-5  
Fax +49 941 850-1002  
www.osram-os.com

**Affected Device**

KP CSLNM1.F1

KW CSLNM1.TG

KR CSLNM1.23

KB CSLNM1.14

KP CSLPM1.F1

KW CSLPM1.TG