

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	001	020070210000002431	6160.0002	Connector	2562 Appliance Inlet C6	n/a
				6160.0034		2562 Appliance Inlet C6	n/a
				6160.0078		2562 Appliance Inlet C6	n/a
				6160.0081		2562 Appliance Inlet C6	n/a


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

UL upgrade from UL 498 to UL 60320-1.

Marking for UL rating 7A/125V~ added. CSA / UR Approval Mark replaced by cURus.

3 Detailed description of change



4 Reason of change

Standards update according to the new UL/CSA 60320-1

5 Release date

The change takes effect in ww 19/2021 (Date code 2119 or higher on label).

6 Impact of change and recommended action

	Yes	Change of approval and rating marking
Form	Yes	Change of approval and rating marking
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet 2562	

Product Change Notification					2562 Change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-054-460
zeierjo	31.03.2021	31.03.2021	muehlema	2020049	C	1 of 1	