

PRODUCT CHANGE NOTIFICATION

Product Category CABLE MANAGERS 20221006-1

Product Group ROAR

ISSUE DATE: 6-Oct-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Some blanking panels with brush seal pass will be discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

| SCHEDULE FOR CHANGE | Year (YYYY) | Month (MM) | Day (DD) |
|--------------------------------------|-------------|------------|----------|
| New product sample availability date | | | |
| Old product discontinuation date* | 2023 | 1 | 4 |

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

| | | | | |
|----------------------|--|--|--|---|
| ASIA PACIFIC | AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com | CHINA: 400-820-1900 CHN-CustomerService@panduit.com | HONG KONG: 800-965768 CHN-CustomerService@panduit.com | |
| | INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com | INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com | JAPAN: +81-3-6863-6000 JPN-CS@panduit.com | |
| | KOREA: 02-2182-7300 KOR-CustomerService@panduit.com | MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com | SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com | |
| | TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com | THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com | | |
| | LATIN AMERICA | BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com | MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com | OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com |
| NORTH AMERICA | USA & CANADA: 1-800-777-3300 cs@panduit.com | EMEA FORM C2-1003 DATE: 06APR21 APPR: MURILLO | EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com | |

IMPACTED PART NUMBER(s)

BR1W

BR2W