

PRODUCT CHANGE NOTIFICATION

Product Category POWER AND CONNECTIVITY 20210209-2

Product Group INTELLIGENT INFRASTRUCTURE

ISSUE DATE: 20210209

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The SmartZone Security Handles are replacing the legacy electronic swinghandles. The new handles feature dual freq. readers, status and beacon LEDs and are in many ways backwards compatible. However, as different harnesses must be used please pay careful attention to the documentation and diagrams found in the spec sheets and user manuals. G5 PDU Firmware Version 3.x required.



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	2	8
Old product discontinuation date*	2021	5	31

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Impacted Part Numbers	Compatibility Type	Replacement Part 1	Replacement Part 2
ACE01	Complex	ACF05	
ACE02	Complex	ACF05	
ACE03	Complex	ACF05	
ACF20-A	No Replacement	NO-REPLACEMENT	
ACB01	Complex	ACF20	MA030
ACB02	Complex	ACF20	MA030
ACB03	Complex	ACF20	MA030
ACB04	Complex	ACF20	MA030
ACB05	Complex	ACF20	MA030
KE001X	No Replacement	NO-REPLACEMENT	
KE006X	No Replacement	NO-REPLACEMENT	
KE007X	No Replacement	NO-REPLACEMENT	
KE008X	No Replacement	NO-REPLACEMENT	
KE010X	No Replacement	NO-REPLACEMENT	
KE011X	No Replacement	NO-REPLACEMENT	
TU001X	No Replacement	NO-REPLACEMENT	
TU006X	No Replacement	NO-REPLACEMENT	
TU007X	No Replacement	NO-REPLACEMENT	
TU008X	No Replacement	NO-REPLACEMENT	
TU010X	No Replacement	NO-REPLACEMENT	
TU011X	No Replacement	NO-REPLACEMENT	
DHSCSH-03/N	Complex	ACF05	
DHSCSH-04	Complex	ACF05	
DHSCSH-04/N	Complex	ACF05	
DHSCSH-05	Complex	ACF05	
DHSCSH-05/N	Complex	ACF05	
DHSCSH-06/N	Complex	ACF05	
DHSCSH-07/N	Complex	ACF05	
DHSCSH-08/N	Complex	ACF05	