

## Product Discontinuation

### PDN-ION-2705-2018

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ION - I/O and Networks	DNC	Product Discontinuation	Notify Distributors and Field	10/31/2018

*Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.*

#### Description for Product Discontinuation

Phoenix Contact has discontinued the SUBCON 37-pin male and female devices. The supplier of the 37-pin D-SUB has discontinued their offering forcing an immediate discontinuation of the SUBCONS listed below. Currently, there is no replacement available.

#### Stock Status

Can existing stock still be used?	Yes
Is mixture of stock acceptable?	No

#### Transaction Dates

Last Buy from Phoenix Contact:	10/31/2018
Last Scheduled Ship from Phoenix Contact:	10/31/2018

*Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.*

#### Contact Info:

Jason Haldeman  
jhaldeman@phoenixcon.com

Thank you,

Ira Sharp

Product Marketing Manager, I/O and Network



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300  
Fax: 717-944-1625

## Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
2300973	SUBCON 37/M-SH		
2300986	SUBCON 37/F-SH		