

Global Change Notification (GCN)

Product Family	Mini Fit BMI	10713617
		GCN Number
Series	43810	September 14, 2015
		Date Issued
Reason For Change	Product Component Change	
Change Description	This letter is to inform you that Molex will be increasing the tail length of the back row/long pins to better match the tail length of front row/short pins on the header part numbers listed. There will be no change to the front row/short pin. This will improve tail length consistency and improve manufacturing efficiency. No change to the form fit or function of the part. This will be a running change and the sales drawing will not change.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes	
Assessment Of Change (How Product Will Be Qualified & Validated)	This change will improve the tail length consistency.	
Internal Molex Qualification Date (Planned Date Information Available)	August 26, 2015	
Sample Availability Date (Changed Part)	October 06, 2015	
Date of Implementation	October 06, 2015	
Method of Identifying Change	Date on the manufacturing label	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com