

Product Discontinuation

PDN-ICC-6388-2020

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ICC - Industrial Cabinet	BE5	Product Discontinuation	Notify Distributors and Field	12/9/2020

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

The Barrier (BT) product line developed specifically for the East Asian market will be discontinued for strategic market reasons. There is not a 100% equivalent in the Phoenix Contact product range. Many other terminal blocks, however, are available as alternatives in push-in, screw, and bolt connection technologies. Get in touch with your local sales contact for more information or questions.

Stock Status

Can existing stock still be used?	Yes
Is mixture of stock acceptable?	No

Transaction Dates

Last Buy from Phoenix Contact:	11/30/2021
Last Scheduled Ship from Phoenix Contact:	12/31/2021

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Eric Silvestri
esilvestri@phoenixcontact.com

Thank you,

Alan Sappe

Product Marketing Manager - Industrial Cabinet Conn.



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
3281176	BT 14		
3281110	BT 2,0-F		
3281117	BT 3,5-F		
3281133	BT 5,5		
3281118	BTH 3,5-F		
3281182	BTO 14		
3281200	BTO 38		
3281139	BTO 5,5		
3281188	D-BT 14		
3281145	D-BT 5,5		
3281116	BTP 3,5		
3281101	BTH 1,25		
3281100	BTO 1,25		
3281107	BTO 2,0		
3281120	D-BT 1,25		
3281121	D-BT 3,5		
3281128	BTP 3,5 GY		
3281108	BTH 2,0		
3281102	BTP 1,25		
3281130	D-BT 3,5 GY		
3281123	BT 2,0		
3281114	BTO 3,5		
3281122	BT 1,25		
3281109	BTP 2,0		
3281124	BT 3,5		
3281125	AP-BTO 1,25		