

## Product Change Notice

PCN#: EE-PCN22002

1/12/2022

### CLASSIFICATION OF CHANGE:

End of Life

### DESCRIPTION OF CHANGE:

The TCP70 series of fuses have reached end of life. There are no drop-in replacements, but alternatives can be suggested. Please contact [ELXTechSupport@Eaton.com](mailto:ELXTechSupport@Eaton.com), [Contact Us](#) or your local Eaton sales representative to find a suitable alternative for your application

### REASON FOR CHANGE:

Due to low sales volume the product has reached end of life.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

N/A

### PARTS FAMILIES AFFECTED

Part Number
BK1-TCP70-10-R
BK1-TCP70-15-R
BK1-TCP70-30-R
BK1-TCP70-5-R
BK1-TCP70-6-R

### TIME SCHEDULE:

Effective immediately

### ISSUED BY:

Jenan Krouchick  
Product Manager – Circuit Protection

### CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).