

Product Obsolescence Notification

Issue Date: June 29, 2018

Dear [CUSTOMER]:

On Feb 1, 2018 Broadcom released Product Change Notice PCN-STB-43088-027-0 which stated that Broadcom is moving from Global Foundries to TSMC as the primary foundry source for BCM33843 and BCM3384 products. This Product Obsolescence Notice is to clarify that Broadcom will EOL Global Foundries as a foundry source for BCM33843 and BCM3384. The last shipment of Global Foundry based material is expected to occur by January 31, 2019. Until then or until instructed by Broadcom, orders should continue to be placed on existing GF part numbers. TSMC remains and will remain as an active foundry source for these products. BCM33843 and BCM3384 products sourced from TSMC are not EOL and continue to be supported.

Broadcom Part Numbers (GF)	LTB Date	LTS Date	Minimum Order (MOQ)	Suggested Replacement (TSMC)
BCM33843DKFSBG	9/30/2018	1/31/2019	5,000	BCM33843DUKFSBGB0T
BCM33843DIFSBG	9/30/2018	1/31/2019	5,000	BCM33843DUIFSBGB0T
BCM33843DUKFSBG	9/30/2018	1/31/2019	5,000	BCM33843DUKFSBGB0T
BCM33843DUIFSBG	9/30/2018	1/31/2019	5,000	BCM33843DUIFSBGB0T
BCM33843EKFSBG	9/30/2018	1/31/2019	5,000	BCM33843EUKFSBGB0T
BCM33843EUKFSBG	9/30/2018	1/31/2019	5,000	BCM33843EUKFSBGB0T
BCM33843GKFSBG	9/30/2018	1/31/2019	5,000	BCM33843GUKFSBGB0T
BCM33843GIFSBG	9/30/2018	1/31/2019	5,000	BCM33843GUKFSBGB0T
BCM33843GUIFSBG	9/30/2018	1/31/2019	5,000	BCM33843GUIFSBGB0T
BCM33843GUKFSBG	9/30/2018	1/31/2019	5,000	BCM33843GUKFSBGB0T
BCM33843MKFSBG	9/30/2018	1/31/2019	5,000	BCM33843MKFSBGB0T
BCM33843MRKFSBG	9/30/2018	1/31/2019	5,000	BCM33843MRKFSBGB0T
BCM33843MVKFSBG	9/30/2018	1/31/2019	5,000	BCM33843MVFBSBGB0T
BCM33843VKFSBG	9/30/2018	1/31/2019		N/A
BCM33843VUKFSBG	9/30/2018	1/31/2019		N/A
BCM33843ZKFSBG	9/30/2018	1/31/2019	5,000	BCM33843ZUKFSBGB0T
BCM33843ZUKFSBG	9/30/2018	1/31/2019	5,000	BCM33843ZUKFSBGB0T
BCM3384DKFSBG	9/30/2018	1/31/2019	5,000	BCM3384DUKFSBGB0T
BCM3384DIFSBG	9/30/2018	1/31/2019	5,000	BCM3384DUIFSBGB0T
BCM3384DUKFSBG	9/30/2018	1/31/2019	5,000	BCM3384DUKFSBGB0T
BCM3384DUIFSBG	9/30/2018	1/31/2019	5,000	BCM3384DUIFSBGB0T
BCM3384EKFSBG	9/30/2018	1/31/2019	5,000	BCM3384EUKFSBGB0T
BCM3384EUKFSBG	9/30/2018	1/31/2019	5,000	BCM3384EUKFSBGB0T
BCM3384EDUKFSBG	9/30/2018	1/31/2019		N/A
BCM3384GKFSBG	9/30/2018	1/31/2019	5,000	BCM3384GUKFSBGB0T
BCM3384GIFSBG	9/30/2018	1/31/2019	5,000	BCM3384GUIFSBGB0T
BCM3384GUKFSBG	9/30/2018	1/31/2019	5,000	BCM3384GUKFSBGB0T
BCM3384GUIFSBG	9/30/2018	1/31/2019	5,000	BCM3384GUIFSBGB0T
BCM3384MKFSBG	9/30/2018	1/31/2019	5,000	BCM3384MKFSBGB0T
BCM3384MDKFSBG	9/30/2018	1/31/2019		N/A
BCM3384MVKFSBG	9/30/2018	1/31/2019	5,000	BCM3384MVKFSBGB0T
BCM3384ZKFSBG	9/30/2018	1/31/2019	5,000	BCM3384ZUKFSBGB0T
BCM3384ZDKFSBG	9/30/2018	1/31/2019	5,000	BCM3384ZDUKFSBGB0T
BCM3384ZDUKFSBG	9/30/2018	1/31/2019	5,000	BCM3384ZDUKFSBGB0T
BCM3384ZUKFSBG	9/30/2018	1/31/2019	5,000	BCM3384ZUKFSBGB0T



Please provide your Broadcom Inc. Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy order (LTB) date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the LTS date noted in the above table. Due to inherent variations in yields, Broadcom Inc. reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom Inc.'s obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom Inc.'s minimum order quantity requirements per the above table. All prior commitments regarding Broadcom Inc. minimum order requirements do not apply to last time buy orders. Broadcom Inc. reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.