



Title of Change:	Packing Change for SOIC-8 MSL 1 products.		
Effective date:	20 December 2018		
Contact information:	Contact your local ON Semiconductor Sales Office or < Erik.Comparini@onsemi.com >		
Type of notification:	This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin.		
Change Category:	<input type="checkbox"/> Wafer Fab <input type="checkbox"/> Assembly Change <input type="checkbox"/> Test Change <input checked="" type="checkbox"/> Other <u>Packing</u>		
Change Sub-Category(s):	<input type="checkbox"/> Manufacturing Site Addition <input type="checkbox"/> Material Change <input type="checkbox"/> Datasheet/Product Doc change <input type="checkbox"/> Manufacturing Site Transfer <input type="checkbox"/> Product specific change <input checked="" type="checkbox"/> Shipping/Packaging/Marking <input type="checkbox"/> Manufacturing Process Change <input type="checkbox"/> Other: _____		
Sites Affected:	ON Semiconductor Sites: ON Carmona, Philippines ON Tarlac City, Philippines	External Foundry/Subcon Sites: ASE Kunshan GEM Greatek Stars Hana	
Description and Purpose:			
SOIC-8 MSL 1 products will be packed two reels per intermediate box in order to optimize dimensional shipping weight and reduce waste. There is no change to the form, fit or function of the product. There is no change in box size or box specification. Customers may continue to order single reel increments with no change in box size or packing. If customers order in multiples of two reels, the reels will be packed two reels per intermediate box.			
List of Affected Parts:			
FAN301ULMY	MC78L05ACDR2G	LM358ADR2G	NCS1002DR2G
FAN302HLMY-F117	MC78L08ABDR2G	LM358DR2G	NCS20032DR2G
FAN302ULMY	MC78L08ACDR2G	LM358EDR2G	NCS20062DR2G
SMC0417	MC78L09ABDR2G	LM392DR2G	NCS20072DR2G
SMC0517	MC78L09ACDR2G	LM393DR2G	NCS20082DR2G
SMC0617	MC78L12ABDR2G	LM393DR2GH	NCS20092DR2G
NCP382HD05AAR2G	MC78L12ACDR2G	LM393EDR2G	NCS2211DR2G
NCP382HD10AAR2G	MC78L15ABDR2G	LM833DR2G	NCS2553DR2G
NCP382HD15AAR2G	MC78L15ACDR2G	LMV358DR2G	NCS2563DR2G
NCP382LD05AAR2G	MC79L05ABDR2G	LMV393DR2G	NCS3402DR2G
NCP382LD10AAR2G	MC79L05ACDR2G	LMV932DR2G	NE5230DR2G
NCP382LD15AAR2G	MC79L12ABDR2G	MC1455BDR2G	NE5532AD8R2G
LM2931ACDR2G	MC79L12ACDR2G	MC1455DR2G	NE5532D8R2G
LM2931AD-5.0R2G	MC79L15ABDR2G	MC33071ADR2G	NE5534ADR2G



LM2931CDR2G	MC79L15ACDR2G	MC33071DR2G	NE5534DR2G
LM2931D-5.0R2G	NCP3334DADJR2G	MC33072ADR2G	NE592D8R2G
LM317LBDR2G	NCP5500DADJR2G	MC33072DR2G	SA5230DR2G
LM317LDR2G	SC79L05ABDR2G	MC33077DR2G	SA5534ADR2G
LP2951ACD-3.0R2G	CAT4104V-GT3	MC33078DR2G	SCY33178DR2G
LP2951ACD-3.3R2G	FMC33202DR2G	MC33171DR2G	SCY33202VDR2G
LP2951ACDR2G	LM201ADR2G	MC33172DR2G	SE5230DR2G
LP2951CD-3.0R2G	LM201AVDR2G	MC33172VDR2G	SE5532AD8R2G
LP2951CD-3.3R2G	LM211DR2G	MC33178DR2G	TS393DR2G
LP2951CDR2G	LM258DR2G	MC33201DR2G	MC78L05ABDR2G
MC33269DR2-012G	LM2903DR2G	MC33201VDR2G	MC33375D-3.3R2G
MC33269DR2-3.3G	LM2903DR2GH	MC33202DR2G	MC33375D-5.0R2G
MC33269DR2-5.0G	LM2903EDR2G	MC33202VDR2G	LM301ADR2G
MC33269DR2G	LM2903VDR2G	MC33272ADR2G	LM311DR2G
MC33275D-2.5R2G	LM2904DR2G	MC34071ADR2G	MC34072VDR2G
MC33275D-3.3R2G	LM2904EDR2G	MC34071DR2G	NCS1002ADR2G
MC33275D-5.0R2G	LM2904VDR2G	MC34072ADR2G	LM293DR2G
			MC34072DR2G

NOTE:

Please be informed that there are Customer Specific parts impacted by this notice, thus MPN & CPN info will not be reflected in the parts list of this Generic document. Instead please click the link to the addendum copy provided in the email notification to see full list of affected products specific to your company.

Japanese translation of the notification starts here.
通知の日本語訳はここから始まります。

Note: The Japanese version is for reference only. In case of any differences between the English and Japanese version, the English version shall control.

注：日本語版は参照用です。英語版と日本語版の違いがある場合は、英語版が優先されます。



変更の件名:	SOIC-8 MSL 1 製品のパッキング変更。																																																																										
発効日:	20 December 2018																																																																										
連絡先情報:	現地のオン・セミコンダクター営業所または<Erik.Comparini@onsemi.com>にお問い合わせください。																																																																										
通知の種類:	本製品速報は通知目的のみのものです。オン・セミコンダクターは本製品速報の発行により本変更を実行します。																																																																										
変更カテゴリ:	<input type="checkbox"/> ウェハファブの変更 <input type="checkbox"/> アセンブリの変更 <input type="checkbox"/> 試験の変更 <input checked="" type="checkbox"/> その他 <u>パッキング</u>																																																																										
変更サブカテゴリ:	<input type="checkbox"/> 製造拠点の追加 <input type="checkbox"/> 材料の変更 <input type="checkbox"/> データシート/製品資料の変更 <input type="checkbox"/> 製造拠点の移転 <input type="checkbox"/> 製品仕様の変更 <input checked="" type="checkbox"/> 出荷/パッケージング/表記 <input type="checkbox"/> 製造プロセスの変更 <input type="checkbox"/> その他:																																																																										
影響を受ける拠点:	オン・セミコンダクター 拠点: ON Carmona, Philippines ON Tarlac City, Philippines	外部ファウンドリまたは下請け業者 拠点: ASE Kunshan GEM Greatek Stars Hana																																																																									
説明および目的:	SOIC-8 MSL 1 製品の梱包を、輸送重量の最適化、廃棄物の削減のため、中間ボックスあたり 2 リールにします。製品の形状、適合性、機能に変更はありません。ボックスサイズなどボックスの仕様に変更はありません。顧客は、ボックスサイズや梱包の変更をともなわないシングルリールの注文もできますが、2 リールの倍数で注文した場合、中間ボックスあたり 2 リールが梱包されます。																																																																										
影響を受ける部品の一覧:	<table border="0"> <tr> <td>FAN301ULMY</td> <td>MC78L05ACDR2G</td> <td>LM358ADR2G</td> <td>NCS1002DR2G</td> </tr> <tr> <td>FAN302HLMY-F117</td> <td>MC78L08ABDR2G</td> <td>LM358DR2G</td> <td>NCS20032DR2G</td> </tr> <tr> <td>FAN302ULMY</td> <td>MC78L08ACDR2G</td> <td>LM358EDR2G</td> <td>NCS20062DR2G</td> </tr> <tr> <td>SMC0417</td> <td>MC78L09ABDR2G</td> <td>LM392DR2G</td> <td>NCS20072DR2G</td> </tr> <tr> <td>SMC0517</td> <td>MC78L09ACDR2G</td> <td>LM393DR2G</td> <td>NCS20082DR2G</td> </tr> <tr> <td>SMC0617</td> <td>MC78L12ABDR2G</td> <td>LM393DR2GH</td> <td>NCS20092DR2G</td> </tr> <tr> <td>NCP382HD05AAR2G</td> <td>MC78L12ACDR2G</td> <td>LM393EDR2G</td> <td>NCS2211DR2G</td> </tr> <tr> <td>NCP382HD10AAR2G</td> <td>MC78L15ABDR2G</td> <td>LM833DR2G</td> <td>NCS2553DR2G</td> </tr> <tr> <td>NCP382HD15AAR2G</td> <td>MC78L15ACDR2G</td> <td>LMV358DR2G</td> <td>NCS2563DR2G</td> </tr> <tr> <td>NCP382LD05AAR2G</td> <td>MC79L05ABDR2G</td> <td>LMV393DR2G</td> <td>NCS3402DR2G</td> </tr> <tr> <td>NCP382LD10AAR2G</td> <td>MC79L05ACDR2G</td> <td>LMV932DR2G</td> <td>NE5230DR2G</td> </tr> <tr> <td>NCP382LD15AAR2G</td> <td>MC79L12ABDR2G</td> <td>MC1455BDR2G</td> <td>NE5532AD8R2G</td> </tr> <tr> <td>LM2931ACDR2G</td> <td>MC79L12ACDR2G</td> <td>MC1455DR2G</td> <td>NE5532D8R2G</td> </tr> <tr> <td>LM2931AD-5.0R2G</td> <td>MC79L15ABDR2G</td> <td>MC33071ADR2G</td> <td>NE5534ADR2G</td> </tr> <tr> <td>LM2931CDR2G</td> <td>MC79L15ACDR2G</td> <td>MC33071DR2G</td> <td>NE5534DR2G</td> </tr> <tr> <td>LM2931D-5.0R2G</td> <td>NCP3334DADJR2G</td> <td>MC33072ADR2G</td> <td>NE592D8R2G</td> </tr> <tr> <td>LM317LBD2G</td> <td>NCP5500DADJR2G</td> <td>MC33072DR2G</td> <td>SA5230DR2G</td> </tr> <tr> <td>LM317LDR2G</td> <td>SC79L05ABDR2G</td> <td>MC33077DR2G</td> <td>SA5534ADR2G</td> </tr> </table>			FAN301ULMY	MC78L05ACDR2G	LM358ADR2G	NCS1002DR2G	FAN302HLMY-F117	MC78L08ABDR2G	LM358DR2G	NCS20032DR2G	FAN302ULMY	MC78L08ACDR2G	LM358EDR2G	NCS20062DR2G	SMC0417	MC78L09ABDR2G	LM392DR2G	NCS20072DR2G	SMC0517	MC78L09ACDR2G	LM393DR2G	NCS20082DR2G	SMC0617	MC78L12ABDR2G	LM393DR2GH	NCS20092DR2G	NCP382HD05AAR2G	MC78L12ACDR2G	LM393EDR2G	NCS2211DR2G	NCP382HD10AAR2G	MC78L15ABDR2G	LM833DR2G	NCS2553DR2G	NCP382HD15AAR2G	MC78L15ACDR2G	LMV358DR2G	NCS2563DR2G	NCP382LD05AAR2G	MC79L05ABDR2G	LMV393DR2G	NCS3402DR2G	NCP382LD10AAR2G	MC79L05ACDR2G	LMV932DR2G	NE5230DR2G	NCP382LD15AAR2G	MC79L12ABDR2G	MC1455BDR2G	NE5532AD8R2G	LM2931ACDR2G	MC79L12ACDR2G	MC1455DR2G	NE5532D8R2G	LM2931AD-5.0R2G	MC79L15ABDR2G	MC33071ADR2G	NE5534ADR2G	LM2931CDR2G	MC79L15ACDR2G	MC33071DR2G	NE5534DR2G	LM2931D-5.0R2G	NCP3334DADJR2G	MC33072ADR2G	NE592D8R2G	LM317LBD2G	NCP5500DADJR2G	MC33072DR2G	SA5230DR2G	LM317LDR2G	SC79L05ABDR2G	MC33077DR2G	SA5534ADR2G
FAN301ULMY	MC78L05ACDR2G	LM358ADR2G	NCS1002DR2G																																																																								
FAN302HLMY-F117	MC78L08ABDR2G	LM358DR2G	NCS20032DR2G																																																																								
FAN302ULMY	MC78L08ACDR2G	LM358EDR2G	NCS20062DR2G																																																																								
SMC0417	MC78L09ABDR2G	LM392DR2G	NCS20072DR2G																																																																								
SMC0517	MC78L09ACDR2G	LM393DR2G	NCS20082DR2G																																																																								
SMC0617	MC78L12ABDR2G	LM393DR2GH	NCS20092DR2G																																																																								
NCP382HD05AAR2G	MC78L12ACDR2G	LM393EDR2G	NCS2211DR2G																																																																								
NCP382HD10AAR2G	MC78L15ABDR2G	LM833DR2G	NCS2553DR2G																																																																								
NCP382HD15AAR2G	MC78L15ACDR2G	LMV358DR2G	NCS2563DR2G																																																																								
NCP382LD05AAR2G	MC79L05ABDR2G	LMV393DR2G	NCS3402DR2G																																																																								
NCP382LD10AAR2G	MC79L05ACDR2G	LMV932DR2G	NE5230DR2G																																																																								
NCP382LD15AAR2G	MC79L12ABDR2G	MC1455BDR2G	NE5532AD8R2G																																																																								
LM2931ACDR2G	MC79L12ACDR2G	MC1455DR2G	NE5532D8R2G																																																																								
LM2931AD-5.0R2G	MC79L15ABDR2G	MC33071ADR2G	NE5534ADR2G																																																																								
LM2931CDR2G	MC79L15ACDR2G	MC33071DR2G	NE5534DR2G																																																																								
LM2931D-5.0R2G	NCP3334DADJR2G	MC33072ADR2G	NE592D8R2G																																																																								
LM317LBD2G	NCP5500DADJR2G	MC33072DR2G	SA5230DR2G																																																																								
LM317LDR2G	SC79L05ABDR2G	MC33077DR2G	SA5534ADR2G																																																																								



LP2951ACD-3.0R2G	CAT4104V-GT3	MC33078DR2G	SCY33178DR2G
LP2951ACD-3.3R2G	FMC33202DR2G	MC33171DR2G	SCY33202VDR2G
LP2951ACDR2G	LM201ADR2G	MC33172DR2G	SE5230DR2G
LP2951CD-3.0R2G	LM201AVDR2G	MC33172VDR2G	SE5532AD8R2G
LP2951CD-3.3R2G	LM211DR2G	MC33178DR2G	TS393DR2G
LP2951CDR2G	LM258DR2G	MC33201DR2G	MC78L05ABDR2G
MC33269DR2-012G	LM2903DR2G	MC33201VDR2G	MC33375D-3.3R2G
MC33269DR2-3.3G	LM2903DR2GH	MC33202DR2G	MC33375D-5.0R2G
MC33269DR2-5.0G	LM2903EDR2G	MC33202VDR2G	LM301ADR2G
MC33269DR2G	LM2903VDR2G	MC33272ADR2G	LM311DR2G
MC33275D-2.5R2G	LM2904DR2G	MC34071ADR2G	MC34072VDR2G
MC33275D-3.3R2G	LM2904EDR2G	MC34071DR2G	NCS1002ADR2G
MC33275D-5.0R2G	LM2904VDR2G	MC34072ADR2G	LM293DR2G
			MC34072DR2G

注: 本通知により影響を受ける顧客特定部品があり、よって MPN および CPN 情報は本一般文書の部品リストに反映していないことにご留意ください。代わりに、特に御社に影響する製品の全リストを見るためには電子メール通知で提供される補遺コピーへのリンクをクリックしてください。



Appendix A: Changed Products

Product	Customer Part Number
CAT4104V-GT3	
FAN302HLMY-F117	
FAN302ULMY	
LM201ADR2G	
LM201AVDR2G	
LM211DR2G	
LM258DR2G	
LM2903DR2G	
LM2903EDR2G	
LM2903VDR2G	
LM2904DR2G	
LM2904EDR2G	
LM2904VDR2G	
LM2931ACDR2G	
LM2931AD-5.0R2G	
LM2931CDR2G	
LM2931D-5.0R2G	
LM293DR2G	
LM301ADR2G	
LM311DR2G	
LM317LBDR2G	
LM317LDR2G	
LM358ADR2G	
LM358DR2G	
LM358EDR2G	
LM392DR2G	
LM393DR2G	
LM393DR2GH	
LM393EDR2G	
LM833DR2G	
LMV358DR2G	
LMV393DR2G	
LMV932DR2G	
LP2951ACD-3.0R2G	
LP2951ACD-3.3R2G	
LP2951ACDR2G	
LP2951CD-3.0R2G	
LP2951CD-3.3R2G	
LP2951CDR2G	
MC1455BDR2G	
MC1455DR2G	
MC33071ADR2G	
MC33071DR2G	
MC33072ADR2G	
MC33072DR2G	
MC33077DR2G	
MC33078DR2G	
MC33171DR2G	
MC33172DR2G	
MC33172VDR2G	
MC33178DR2G	
MC33201DR2G	
MC33201VDR2G	
MC33202DR2G	
MC33202VDR2G	
MC33269DR2-012G	
MC33269DR2-3.3G	
MC33269DR2-5.0G	
MC33269DR2G	



MC33272ADR2G	
MC33275D-2.5R2G	
MC33275D-3.3R2G	
MC33275D-5.0R2G	
MC33375D-3.3R2G	
MC33375D-5.0R2G	
MC34071ADR2G	
MC34071DR2G	
MC34072ADR2G	
MC34072DR2G	
MC34072VDR2G	
MC78L05ABDR2G	
MC78L05ACDR2G	
MC78L08ABDR2G	
MC78L08ACDR2G	
MC78L09ABDR2G	
MC78L09ACDR2G	
MC78L12ABDR2G	
MC78L12ACDR2G	
MC78L15ABDR2G	
MC78L15ACDR2G	
MC79L05ABDR2G	
MC79L05ACDR2G	
MC79L12ABDR2G	
MC79L12ACDR2G	
MC79L15ABDR2G	
MC79L15ACDR2G	
NCP3334DADJR2G	
NCP382HD05AAR2G	
NCP382HD10AAR2G	
NCP382HD15AAR2G	
NCP382LD05AAR2G	
NCP382LD10AAR2G	
NCP382LD15AAR2G	
NCP5500DADJR2G	
NCS1002ADR2G	
NCS1002DR2G	
NCS20032DR2G	
NCS20062DR2G	
NCS20072DR2G	
NCS20082DR2G	
NCS20092DR2G	
NCS2211DR2G	
NCS2553DR2G	
NCS2563DR2G	
NCS3402DR2G	
NE5230DR2G	
NE5532AD8R2G	
NE5532D8R2G	
NE5534ADR2G	
NE5534DR2G	
NE592D8R2G	
SA5230DR2G	
SA5534ADR2G	
SC79L05ABDR2G	
SCY33178DR2G	
SE5230DR2G	
SE5532AD8R2G	
TS393DR2G	