



Product Change Notification

TE Connectivity

Product Change Notification: E-18-016369

PCN Date: 29-OCT-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

DEUTSCH DTF HEADER RECEPTACLE (DTF13-2P/3P/4P/6P/12P)

Description of Changes

Manufacturing location change. The Industrial & Commercial Transportation (ICT) business unit of TE Connectivity (TEC) is adding alternate TEC approved supplier for the pin contacts that are over molded in the header. TEC/ICT will do its due diligence by requiring a PPAP from the supplier. This supplier has been used extensively in the past by TEC business unit with excellent performance.

Reason for Changes:

Dear Customer, we inform you of this alternate supplier as part of our aggressive continuous improvement efforts on delivery. The alternate supplier process is executed by following TE internal strict procedures, which mitigates quality risk while increasing our ability to supply your products on time. The alternate supplier is governed under a TS16949 certified quality management system according to standard automotive requirements. An internal release based on our specifications will be executed before any parts are delivered.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	02-NOV-2018
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	01-JAN-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTF13-12PA	NO			"ZPF00000000130557"			
DTF13-12PB	NO			"ZPF00000000130559"			
DTF13-2P	NO			"ZPF00000000130128"			
DTF13-3P	NO			"ZPF00000000130194"			
DTF13-4P	NO			"ZPF00000000130261"			
DTF13-6P	NO			"ZPF00000000130333"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTF13-12PB	NO			"ZPF00000000130559"			
DTF13-2P	NO			"ZPF00000000130128"			
DTF13-4P	NO			"ZPF00000000130261"			
DTF13-6P	NO			"ZPF00000000130333"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
	NO			"ZPF00000000130559"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTF13-12PB							
DTF13-2P	NO			"ZPF000000000130128"			
DTF13-4P	NO			"ZPF000000000130261"			
DTF13-6P	NO			"ZPF000000000130333"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTF13-12PA	NO			"ZPF000000000130557"			
DTF13-2P	NO			"ZPF000000000130128"			
DTF13-3P	NO			"ZPF000000000130194"			
DTF13-4P	NO			"ZPF000000000130261"			
DTF13-6P	NO			"ZPF000000000130333"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTF13-12PA	NO			"ZPF000000000130557"			
DTF13-2P	NO			"ZPF000000000130128"			
DTF13-3P	NO			"ZPF000000000130194"			
DTF13-4P	NO			"ZPF000000000130261"			
DTF13-6P	NO			"ZPF000000000130333"			