

Issue Date: October 23rd, 2020

Dear Valued Customer,

This notice is to inform you of our efforts in re-sourcing a component used in a finished good that you have purchased from Littelfuse in the past.

Description of the Change:

- We will be insourcing the production of the pin featured in the following finished goods: 00680200, 00680261.05, 00680262, 00680262.05, 00680700, 00680720, 00680800, 00681100, 00681100.01, 00681100.02, 00681160, 00681300, 10820700, 15222200.05, 15222260, 19986100, 70680723, 00524800, 00680800-WBG, 00681100-WBG, and 10820700-FCB.

Reason for The Change:

- The current pin supplier, one who had supplied this component since before Littelfuse's acquisition of Menbers, is one that no longer meets the production or commercial requirements to supply to Littelfuse.
- The proposed supplier of this component is an ISO-certified supplier and already supplies similar components to Littelfuse today.

Effective Date of the Change:

- This will occur as a running change; shipments utilizing the new pin are expected Q1 2021.

What You Need to Do:

- No action is required at this time. This transition in vendors will not result in a change in component or finished good fit, form, or function.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zachary Naughton
Global Product Manager
Littelfuse Commercial Vehicle Products