

+ CORPORATE HEADQUARTERS

707 Dayton Road
PO Box 1040
Ottawa, IL 61350
USA

p: (800) 346-3119
f: (815) 433-5109

+ EUROPEAN HEADQUARTERS

Westlink Commercial Park
Unit 10
Oranmore, Co. Galway
Ireland

p: + 353 91 792444
f: + 353 91 792445

+ CELLULAR PRODUCTS GROUP

Sokolská 71
562 04 Ústí nad Orlicí III.
Czech Republic

p: +420 465 521 020
f: +420 464 647 299

Product EOL Notice

June 29, 2018

Model	Description
BB-856-15711	IMCV-MEDIALINX TX/FX- MM850-ST
BB-856-15713	IMCV-MEDIALINX TX/FX- MM1300-ST
BB-856-15714	IMCV-MEDIALINX TX/FX- MM1300-SC
BB-850-14530	iMcV-S2MM/155,, SM1310/PLUS- SC+MM1300-SC
BB-850-14533	iMcV-S2MM/155, SSFX-SM1550SC +MM1300-SC
BB-850-14555	iMcV-S2MM/155, SM1550/LONG- SC+MM1300-SC
BB-850-14560	iMcV-S2MM/155, SM1310/PLUS- ST+MM850-ST
BB-850-14570	iMcV-S2MM/155, SM1310/PLUS- SC+MM850-SC
BB-859-14799	iMcV-S2MM/1250, LX-SM1310- SC+SX-MM850-SC
BB-859-14800	iMcV-S2MM/1250, LX-SM1310/ PLUS-SC+SX-MM850-SC
BB-859-14801	iMcV-S2MM/1250, LX-SM1550/ LONG-SC+SX-MM850-SC
BB-859-14806	iMcV-S2MM/1250,SSLX-SM1310-SC +SX-MM850-SC(1310XMT/1550RCV)
BB-859-14807	iMcV-S2MM/1250,SSLX-SM1550/ -SC+SX-MM850-SC(1550XMT/1310RC
BB-859-14808	iMcV-S2MM/1250,SSLX-SM1310/ PLUS-SC+SX-MM850-SC
BB-859-14809	iMcV-S2MM/1250,SSLX-SM1550/ PLUS-SC+SX-MM850-SC
BB-859-14822	iMcV-S2SM/1250, SSLX-SM1310/ PLUS-SC + LX-SM1310/PLUS-SC
BB-859-14823	iMcV-S2SM/1250, SSLX-SM1550/ PLUS-SC + LX-SM1310/PLUS-SC
BB-850-15620	IMCV-LIM TX/FX- SM1310/LONG-SC
BB-850-14940	IMCV-PIM, TP/FO-MM850-ST
BB-850-14941	IMCV-PIM TP/FO-MM850-SC
BB-850-14945	IMCV-PIM, TP/FO-SM1310/ PLUS-SC

This is the end-of-life announcement for the products listed above. Last time buy orders will be accepted until September 30, 2018.

Product Migration Path:

Current	Replacement
BB-856-15711	BB-856-18700, BB-808-38101(LC connector)
BB-856-15713	BB-856-18700, BB-808-38102(LC connector)
BB-856-15714	BB-856-18700, BB-808-38102(LC connector)
BB-850-14530	No replacement
BB-850-14533	No replacement
BB-850-14555	No replacement
BB-850-14560	No replacement
BB-850-14570	No replacement
BB-859-14799	No replacement
BB-859-14800	No replacement
BB-859-14801	No replacement
BB-859-14806	No replacement
BB-859-14807	No replacement

**+ CORPORATE
HEADQUARTERS**707 Dayton Road
PO Box 1040
Ottawa, IL 61350
USAp: (800) 346-3119
f: (815) 433-5109

BB-859-14808	No replacement
BB-859-14809	No replacement
BB-859-14822	No replacement
BB-859-14823	No replacement
BB-850-15620	No replacement
BB-850-14940	No replacement
BB-850-14941	No replacement
BB-850-14945	No replacement

**+ EUROPEAN
HEADQUARTERS**Westlink Commercial Park
Unit 10
Oranmore, Co. Galway
Irelandp: + 353 91 792444
f: + 353 91 792445

Contact B+B SmartWorx for availability. Full product documentation is available on our website www.advantech-bb.com, or via our support staff: support@advantech-bb.com

**+ CELLULAR
PRODUCTS GROUP**Sokolská 71
562 04 Ústí nad Orlicí III.
Czech Republicp: +420 465 521 020
f: +420 464 647 299

Thank You,



Stan Simmons | Product Sales Manager