



Not Recommended for New Design: NFC Tag Products (Including Modules/EVB)

NRFND.PG30.2.13.2021

2.13.2021

<p>About This Notice:</p>	<p>Effective immediately, the below NFC Tag products are Not Recommended For New Design due to future discontinuation plans.</p>
<p>Effective Date:</p>	<p>Immediate</p>
<p>Affected Parts and/or Replacements:</p>	<p>PN: MN63Y1214-E1 (NFC Tag LSI) PN: MN63Y3212N1 (Module) PN: MN63Y3212N4 (Module) PN: MN63Y3212N5 (Module) PN: MN63Y3213N1 (Module) PN: MN63Y3214N1 (Module) PN: NFC-TAG-MN63Y1208 (EVB)</p>
<p>Datasheet(s):</p>	<p>https://industrial.panasonic.com/content/data/SC/ds/ds4/MN63Y1214_E.pdf https://industrial.panasonic.com/content/data/SC/ds/ds4/MN63Y3212N1_E.pdf https://industrial.panasonic.com/content/data/SC/ds/ds4/MN63Y3212N4_E.pdf https://industrial.panasonic.com/content/data/SC/ds/ds4/MN63Y3212N5_E.pdf https://industrial.panasonic.com/content/data/SC/ds/ds4/MN63Y3213N1_E.pdf https://industrial.panasonic.com/content/data/SC/ds/ds4/MN63Y3214N1_E.pdf https://industrial.panasonic.com/content/data/SC/ds/ds8/c2/EBC_MN63Y1208_EN.pdf</p>