



CUSTOMER OPERATIONS  
 160 RIO ROBLES  
 SAN JOSE, CA 95134

PDN #: M000974I

DATE: 26-Jul-2019

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX77100PEWL+	MAX77100EWL+	24-Oct-2019	24-Oct-2019	Part can no longer be manufactured
Discontinuance	MAX77100PEWL+T	MAX77100EWL+T	24-Oct-2019	24-Oct-2019	Part can no longer be manufactured
Discontinuance	MAX77756BEWL+G7	MAX77756BEWL+	24-Oct-2019	24-Oct-2019	Part can no longer be manufactured
Discontinuance	MAX77756BEWL+TG7	MAX77756BEWL+T	24-Oct-2019	24-Oct-2019	Part can no longer be manufactured
Discontinuance	MAX8972SEWI+	MAX8972AEWI+	24-Oct-2019	24-Oct-2019	Part can no longer be manufactured
Discontinuance	MAX8972SEWI+T	MAX8972AEWI+T	24-Oct-2019	24-Oct-2019	Part can no longer be manufactured
Discontinuance	MAX8974SEWI+	N/A	24-Oct-2019	24-Oct-2019	Part can no longer be manufactured
Discontinuance	MAX8974SEWI+T	N/A	24-Oct-2019	24-Oct-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019