

PRODUCT CHANGE NOTIFICATION

PCN#: COPPER, OUTLETS, SURFACE RACEWAY **20190912-1**

ISSUE DATE: 9/12/2019

IMPACTED REGIONS: **NA** **EMEA** **LATAM** **AP**

REASON FOR CHANGE: **OTHER** **DISCONTINUATION**

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

Obsolescence of the patch cord plug guard. No replacement part for product



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
PLGUARD-C	
PLGUARD-X	
PLGUARDRD-C	
PLGUARDRD-X	
PLGUARDYL-C	
LGUARDYL-X	