

PCN – Process Change Notification

| | |
|---------|----------------|
| Change: | FXP07.07.0100A |
| Date: | 2016/05/25 |
| Author | Kim Ho |

Affected Products

| Model# | Part Number | Changes |
|---|----------------|----------------------|
| FXP07 Antenna Assembly 100mm 1.13 IPEX MHF1 | FXP07.07.0100A | Amend color of cable |
| | | |
| | | |

Type of Change

- Hardware Modification
 Production Process Advance
 Others – Packaging Rules Changing

Description of Change

- The cable color was changed from white to black.

Schedule

2016, June, Taoglas will input this new packaging rules into production.

Forecast Estimated Transition Date

Jun/2016

Illustration of Change

Old Bom

| | Name | P/N | Material | Finish | QTY |
|---|-----------------------|----------------|------------|-------------|-----|
| 1 | FXP07 PCB | 100111D030009A | FPCB 0.24t | Black | 1 |
| 2 | 1.13 Coaxial Cable | 300315C030000A | FEP | White | 1 |
| 3 | IPEX MHF1 | 204111G000002A | Brass | Gold | 1 |
| 4 | Double-Sided Adhesive | 100111D030009A | 3M 467 | Brown Liner | 1 |

New Bom

| | Name | P/N | Material | Finish | QTY |
|---|-----------------------|----------------|------------|-------------|-----|
| 1 | FXP07 PCB | 100111D030009A | FPCB 0.24t | Black | 1 |
| 2 | 1.13 Coaxial Cable | 300215C020000A | FEP | Black | 1 |
| 3 | IPEX MHF1 | 204111G000002A | Brass | Gold | 1 |
| 4 | Double-Sided Adhesive | 100111D030009A | 3M 467 | Brown Liner | 1 |