

Global Change Notification (GCN)

Product Family 2.0WIRE TO BOARD CLIP 10624794

GCN Number

Series 51094 February 12, 2014

Date Issued

Reason For Change Obsolescence

Change Description This is to inform you of 51094 series obsolescence. The series recently have low sales record. Also, it does not seem that the sales activity is going active in the near future. In addition, the mold die is deteriorating. That is why Molex is to terminate their production. The last order date Molex will receive is set on 24th Dec, 2014. The last shipment date will be 28th Feb, 2015. No replacement items are available. The obsoleted items are as follows. 510940605 510940805 510941005 510941205 510941405 510941605 510941805 510942005 510942205 510942405 510942605 510942805 510943005

--	--

Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception Not Applicable

Assessment Of Change (How Product Will Be Qualified & Validated) Not Applicable

Internal Molex Qualification Date (Planned Date Information Available)

Sample Availability Date (Changed Part)

Date of Implementation February 28, 2015

Method of Identifying Change Not Applicable

Recommended Replacement Parts Not Available

Last Time Buy Date for Obsolete Parts December 31, 2014

Last Time Ship Date for Obsolete Parts February 28, 2015

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com