

**ATTN :** \_\_\_\_\_SEIKO EPSON CORPORATION  
MICRODEVICES Operations Div. TDBU**SUB : FA-118T Carrier Tape Change Notice****Dear Valued Customer,**

Thank you for choosing SEIKO EPSON CORPORATION for your product. EPSON maintains a continuous effort to improve the production and delivery performance of its product. Thus, Epson will change carrier tape of the FA-118T series MHz crystal unit.

**Details are below:**1. Affected Product

FA-118T (Product Number : X1E000251xxxxxx)

2. Change items

Carrier Tape (translucent) change to Conductive Carrier Tape (Black-color)

3. Reason

Prevent the influence of static electricity

4. ScheduleMP: From February, 1<sup>st</sup>, 20155. Conclusion

- This change will not affect the form, fit or function, quality, or reliability of the product.
- If you have any concerns and/or requests, please contact your regional SEIKO EPSON CORP TD Sales office.

Sincerely yours,

Seiko Epson Corporation  
Microdevices Operations Div. TDBU