

## Product Change Notice

Date:	June 3, 2022
Overview:	The 620, 8400N, 3300N, 4400 and RL48 series are impacted by a discontinued component. Select models are being discontinued while most will continue to be produced using an alternate component.
Reason for Change:	The motor control IC has become obsolete.
Affected Part No(s):	Please see attached.
Design Change Detail:	The motor control IC for the 620, 8400N, 3300N, 4400 and RL48 series has become obsolete. Select models with low global usage will be discontinued while most models will remain active utilizing an alternate design. The updated design will feature new PCBAs and modified windings for use with the replacement motor control IC. Part numbers will remain the same.
Effective Date:	Running change beginning in May of 2022.
Last Time Buy Deadline:	June 24, 2022 for the models going EOL (please see below for specific part numbers).
Pricing:	No change
ebm-papst employee:	Regina Cleaves
Attachments:	Affected part numbers (detailed on pages 2 & 3 of this PCN).
Comments:	The form, fit, function, and air performance of the updated models will remain the same. Additionally, the new design will provide significantly improved motor efficiency and therefore a reduction in power consumption.

**Models Being Discontinued**

(LTB June 24, 2022)

624  
3314N/2NU-00185  
3414N/2HPU-621  
4312N/12M  
4314N/12N  
4314NMS-717  
4314NN-740  
4314NNR-750  
4314NNU-741  
4314NNU-754  
4412/12M  
4414M-574  
4414MLR-567  
4414N-577  
512F/2P-557  
612N/2HHPR-306  
614F/39H-691  
622/2  
624/2HHP-077  
624NR-060  
8452/2M  
8452/2HP-015  
AC3200JLU  
AC3200JLLU  
RLF35-8/12N/2P-103

## Models Remaining Active (with updated design)

3312N/2N	4414/12M	622HH
3312NH	4414/12N-540	622HH-025
3312NHHU	4414/2M-532	622/2HH-075
3312NL	4414/2M-564	622/2HHP-021
3312NM	4414/2MR-624	622/2HHP-027
3312NN	4414/2N-522	622/2HP-043
3312NN-134	4414/39L3	622/2MP-044
3312NNR	4414/39M	622/2HHP-00242
3312NNU	4414/39MU-598	622/2HHP-00252
3314N/2N	4414/39N	622/2MP-082
3314N/2NU	4414L	622/2MP-103
3314NH	4414L3	622/2NP
3314NL	4414LL	622HHR
3314NL-151	4414LR-00227	624H
3314NM	4414M	624HH
3314NN	4414M-00294	624HHR
3314NNR-127	4414M-521	624HR
3314NNS-133	4414M-556	624N-054
3314NNU	4414M-566	624/2HHP-00093
3314NNU-138	4414M-593	624/2HHP-085
3314NNU-147	4414ML	624/39HHPR-048
4412/2N	4414MLR-580	624/39HHPR-074
4412L	4414MR	624/39HHP
4412LLR-541	4414MU	624/39HR-072
4412LR	4414MU-628	8414N/2HP
4412LU	4414N	8414N/2HP-587
4412M	4414N-00094	8414N/2HP-607
4412ML	4414N-615	8414N/2HPR-612
4412MR	4414N-630	RL48-19/12/2P-00048
4412N	622H	RL48-19/12/2P-026
4412N-617	622HH	

No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing